

15617

Dependent Resurvey, Portion of Subdivisional Lines,
T. 29 S., R. 3 W., Willamette Meridian, Oregon

CHAINS

N 1/16
S 16|S 15
1975

from which

A fir, 10 ins. diam., bears N. 52° E., 2 lks.
dist., mkd. N 1/16 S15 BT.

A fir, 10 ins. diam., bears N. 36° W., 6 lks.
dist., mkd. N 1/16 S16 BT.

Ascend 120 ft. over SE. slope, through light to moderate
timber and heavy undergrowth.

26.85 Dirt road, 15 lks. wide, bears N. 52° E. and S. 46° W.

28.60 Dirt road, 15 lks. wide, bears N. 80° E. and S. 80° W.

35.55 Spur, slopes SW., also dirt road, 15 lks. wide, bears E.
and W.; desc. 15 ft. over NW. slope.

39.90 The cor. of secs. 9, 10, 15, and 16, perpetuated and re-
corded by James W. Byron, Deputy County Surveyor, in 1962,
monumented with an iron pipe, 1½ ins. diam., firmly set,
projecting 12 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 29 S
S 9|S 10 R
S 16|S 15 3
W

BLM 1966
1962

from which the remains of the original bearing trees

A root hole, bears N. 44° E., 56 lks. dist.

A madrone snag, 22 ins. diam., bears S. 25° E.,
46 lks. dist., with scribe marks BT visible
on opened blaze.

A fir snag, 10 ins. diam., bears S. 85° W., 50
lks. dist., with scribe marks BT visible on
opened blaze.

A fir, 20 ins. diam., bears N. 85° W., 47 lks.
dist., with healed blaze.

and bearing trees mkd. by Byron

A pine, 12 ins. diam., bears N. 34° E., 53 lks.
dist., with healed blaze.

A cedar, 18 ins. diam., bears S. 22° E., 37½ lks.
dist., with fragmentary scribe marks visible on
partially healed blaze.

A chinquapin, 10 ins. diam., bears S. 46° W., 19
lks. dist., with healed blaze. (Record, myrtle,
S. 48° W., 16½ lks.)

Land, mountainous.
Soil, rocky clay.