

15619

Dependent Resurvey, Portion of Subdivisional Lines,
T. 29 S., R. 3 W., Willamette Meridian, Oregon

CHAINS

From this point, a local cor. established by Byron, in 1962, bears N. $20\frac{1}{2}^{\circ}$ W., 3 lks. dist., monumented with an iron pipe, $1\frac{1}{2}$ ins. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 29 S	R
$\frac{1}{2}$ S 10	3
S 15	W
1962	

S. $89^{\circ} 32'$ E., beginning new measurement.

Ascend 55 ft. over SW. slope, through moderate timber and heavy undergrowth.

2.00 Ridge, bears N. and S.; desc. 175 ft. over SE. slope.

11.60 County Road No. 18, paved, 35 lks. wide, bears N. 30° E. and S. 30° W.

16.10 South Myrtle Creek, 35 lks. wide, course S. 15° W.; asc. 20 ft. over NW. slope, through heavy timber and undergrowth.

18.60 Point for the E $1/16$ sec. cor. of secs. 10 and 15.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 20 ins. in the ground, with brass cap mkd.

E $1/16$	S 10
	S 15
	1975

from which

A fir, 12 ins. diam., bears N. 55° E., 27 lks. dist., mkd. E $1/16$ S10 BT.

A fir, 10 ins. diam., bears S. 17° E., 50 lks. dist., mkd. E $1/16$ S15 BT.

Ascend 530 ft. over NW. slope.

37.20 The closing cor. of secs. 10 and 15.

From this point, the cor. of secs. 11 and 14 only, bears S. $1^{\circ} 48'$ W., 6.11 chs. dist., hereinbefore described.

Land, mountainous.

Soil, rocky clay.

Timber, fir, cedar, pine, madrone, oak, alder, maple, and dogwood; undergrowth, salal, poison oak, vine maple, hazel, arrowwood, rhododendron, and huckleberry.

Subdivision of Section 15, T. 29 S., R. 3 W.,
Willamette Meridian, Oregon

From the $\frac{1}{4}$ sec. cor. of secs. 15 and 22.

N. $1^{\circ} 56'$ E., on the N. and S. center line of sec. 15.

Ascend 95 ft. over SE. slope, through heavy timber and dense undergrowth.