

Dependent Resurvey of the East Boundary,
T. 31 S., R. 5 W., Willamette Meridian, Oregon

CHAINS

from which the remains of the original bearing trees

A fir, 13 ins. diam., bears S. 10° E., 62 lks. dist., with healed blaze. (Marks reported destroyed by Bushey, in 1894)

A fir stump, 15 ins. diam., bears S. 68° W., 41 lks. dist., with healed blaze.

and the remains of a bearing tree mkd. by Bushey

A root hole, bears N. 60° W., 11 lks. dist., with a down fir alongside, 12 ins. diam., with scribe marks 31 S B visible on opened blaze.

and bearing trees mkd. by Powell

A fir, 25 ins. diam., bears N. 5° E., 23 lks. dist., with healed blaze.

A fir, 13 ins. diam., bears S. 24° W., 7 lks. dist., with healed blaze.

No suitable tree available within limits in sec. 24.

Land, mountainous.
Soil, rocky clay loam.
Timber, fir, hemlock, cedar, madrone, maple, chinquapin, and dogwood; undergrowth, vine maple, hazel, salal, fern, arrowwood, poison oak, and rhododendron.

N. 0° 18' W., along the E. bdy. of sec. 24.

Ascend 60 ft. along E. slope, through logged area and dense undergrowth.

5.89 Point for the closing cor. of secs. 19 and 30, T. 31 S., R. 4 W.; there is no remaining evidence of the original corner. No permanent monument established.

6.10 Spur, slopes E.; desc. 160 ft. over broken SE. slope.

19.91 Point for the S 1/16 sec. cor. of sec. 24 only.

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

S 1/16
S 24|
1973

from which

A hemlock, 6 ins. diam., bears S. 68½° W., 75 lks. dist., mkd. S 1/16 S24 BT.

A cedar, 23 ins. diam., bears N. 36° W., 61½ lks. dist., mkd. S 1/16 S24 BT.

Descend 290 ft. over NE. slope.

22.45 Gravelled road, 15 lks. wide, bears N. 75° W. and S. 75° E.

27.50 Packard Creek, 5 lks. wide, course N. 80° W.; asc. 230 ft. over SW. slope.

34.20 Spur, slopes W.; desc. 85 ft. over NW. slope.