

24

225

15658

Dependent Resurvey, Portion of Subdivisional Lines,
T. 31 S., R. 5 W., Willamette Meridian, Oregon

CHAINS

A hemlock, 10 ins. diam., bears N. 73° E., 65 lks. dist., with healed blaze.

A maple, 12 ins. diam., bears S. 54° W., 121 lks. dist., with scribe marks T31S R5W S35 BT visible on open blaze.

and a new bearing tree

A fir, 16 ins. diam., bears N. 43½° W., 215 lks. dist., mkd. T31S R5W S26 BT.

Land, mountainous.
Soil, rocky clay loam.
Timber, fir, hemlock, cedar, madrone, maple, chinquapin, and live oak; undergrowth, vine maple, hazel, arrowwood, salal, and poison oak.

N. 0° 26' E., bet. secs. 25 and 26.

Descend 120 ft. over NW. slope, across logged area, through light undergrowth.

4.05 Creek, 2 lks. wide, course N. 10° W.; asc. 235 ft. over broken SW. slope. Also enter heavy timber and moderate undergrowth, edge bears E. and W.

14.95 Spur, slopes W.; desc. 195 ft. over N. slope.

20.50 Creek, 1 lk. wide, course S. 85° W.; asc. 380 ft. over broken SW. slope.

39.10 Spur, slopes W.; desc. 65 ft. over N. slope.

39.74 Point for the ¼ sec. cor. of secs. 25 and 26, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 31 S R 5 W

¼
S 26 | S 25
1973

from which

A fir, 25 ins. diam., bears S. 41½° E., 58 lks. dist., mkd. ¼ S25 BT.

A fir, 25 ins. diam., bears N. 17° W., 33½ lks. dist., mkd. ¼ S26 BT.

Descend 530 ft. over broken N. slope.

54.70 Creek, 1 lk. wide, course N. 70° W.; asc. 120 ft. over SW. slope.

60.30 Spur, slopes N. 70° W.; desc. 360 ft. over broken NW. slope.

75.10 Creek, 1 lk. wide, course N. 25° W. Also abandoned Highway No. 99, concrete surfaced, 40 lks. wide, bears N. and S. 15° W.; asc. 20 ft. along abandoned highway.