

15666

Dependent Resurvey, Portion of Subdivisional Lines,
T. 31 S., R. 5 W., Willamette Meridian, Oregon

CHAINS

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

S 12
S 13

T 31 S R 5 W.
1973

from which

A fir, 20 ins. diam., bears N. 28° E., 44 lks. dist., mkd. ¼ S12 BT.

A fir, 14 ins. diam., bears S. 30° E., 25 lks. dist., mkd. ¼ S13 BT.

Descend 370 ft. over NW. slope.

49.80 Frontage road, paved, 30 lks. wide, bears N. 15° E. and S. 15° W.

50.80 Canyon Creek, 10 lks. wide, course N. 15° E.; asc. 250 ft. over SE. slope, across cleared area of Interstate Highway No. 5, right-of-way.

51.60 Center of northbound lanes, Interstate Highway No. 5, 60 lks. wide, bears N. 15° E. and S. 15° W.

52.25 Center of southbound lanes, Interstate Highway No. 5, 60 lks. wide, bears same.

52.60 Enter heavy timber, edge bears same.

60.315 Point for the W 1/16 sec. cor. of secs. 12 and 13.

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

W 1/16 S 12
S 13
1973

from which

A fir, 10 ins. diam., bears N. 27½° E., 19 lks. dist., mkd. W 1/16 S12 BT.

A fir, 8 ins. diam., bears S. 64½° W., 30 lks. dist., mkd. W 1/16 S13 BT.

Ascend 330 ft. over broken SE. slope.

80.42 The cor. of secs. 11, 12, 13, and 14.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock, cedar, madrone, live oak, maple, and chinquapin; undergrowth, vine maple, hazel, arrowwood, salal, fern, and poison oak.

N. 2° 31' E., bet. secs. 11 and 12.

Ascend 140 ft. over SE. slope, through heavy timber and dense undergrowth.