

Survey No. 975 A and B

FEET

OTHER IMPROVEMENTS

A log mine building, used for tool shed, equipment house and camp facilities, the NW corner of which bears S. 20° E., 128 ft. from Cor. No. 2, Mill Site No. 2, 25 x 60 ft. in size; long sides bear north-south claimant herein.

OTHER CORNER DESCRIPTION AND SUPPLEMENTAL DATA

The S. $\frac{1}{4}$ corner of Sec. 34, T. 31 S., R. 2 W., W.M., bears West 342.21 ft. distance from closing corner, Secs. 3-4, T. 32 S., R. 2 W., W.M. The old rock as described in the official record was found to be fractured and the bearing trees non-existent. I reset with a $\frac{1}{2}$ in. pipe, 24 ins. long, 18 ins. in the ground with a 3 ins. diam. brass cap, mkd. S 34, T 31 S, R 2 W; from which

A madrona, 16 ins. diam., bears N. 6° W., 23.4 ft., mkd. $\frac{1}{4}$ S 34, T 31 S, R 2 W, BT.

A fir, 28 ins. diam., bears S. 69° E., 26.5 ft. mkd. $\frac{1}{4}$ S 34, T 31 S, R 2 W, BT.

FIELD ASSISTANTS

<u>Name</u>	<u>Capacity</u>
Jesse Dressler	Chainman
Otto Alley	Chainman
M. B. Jenkins	Chainman