

15791

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 27 S., R. 4 W., Willamette Meridian, Oregon

CHAINS	
	<p>A cedar, 24 ins. diam., bears N. 3° W., 65 lks. dist., with illegible scribe marks visible on open blaze.</p> <p>Land, mountainous. Soil, rocky clay. Timber, fir, cedar, hemlock, pine, yew, maple, alder, madrone, live oak, and chinquapin; undergrowth, vine maple, hazel, rhododendron, manzanita, salal, huckleberry, Oregon grape, and fern.</p>
	<p>From the cor. of secs. 23 and 26 only.</p> <p>N. 89° 52' W., bet. secs. 23 and 26.</p> <p>Descend 190 ft. over NW. slope, through moderate timber and undergrowth.</p>
6.00	Lane Mountain Road, gravelled, 15 lks. wide, bears S. 17° E. and N. 14° W.
10.85	Creek, 5 lks. wide, course N. 42° W.; desc. 20 ft. over NW. slope.
12.30	Creek, 5 lks. wide, course N. 21° W.; asc. 35 ft. over NE. slope.
14.20	Spur, slopes N. 42° W.; desc. 43 ft. over broken NW. slope.
19.73	Ravine, drains N. 10° W.; thence over nearly level land.
19.88	Point for the E 1/16 sec. cor. of secs. 23 and 26.
	<p>Set an iron post, 28 ins. long, 2½ ins. diam., 25 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">E 1/16 <math>\frac{S\ 23}{S\ 26}</math> 1975</p> <p>from which</p> <p>A fir, 8 ins. diam., bears N. 29° E., 38 lks. dist., mkd. E 1/16 S23 BT.</p> <p>A cedar, 12 ins. diam., bears S. 58° W., 35 lks. dist., mkd. E 1/16 S26 BT.</p> <p>Corner is located 72 lks. N. 57° W., of a fence corner, wire fences extend N., E., S., and W.</p> <p>Ascend 10 ft. over NE. slope.</p>
21.35	Spur, slopes N.; desc. 20 ft. over NW. slope.
24.35	Spur, slopes N.; desc. 80 ft. over NW. slope.
30.00	Creek, 5 lks. wide, course N. 20° W.; asc. 15 ft. over NE. slope.
33.15	Spur, slopes N. 19° W.; desc. 10 ft. over NW. slope.
35.40	Ravine, drains N. 6° E.; asc. 5 ft. over NE. slope.
37.50	Spur, slopes N.; desc. 10 ft. over NW. slope.