

15795

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 27 S., R. 4 W., Willamette Meridian, Oregon

## CHAINS

A fir stump, 30 ins. diam., bears N. 71° W., 110 lks. dist., no marks visible.

A fir stump, 36 ins. diam., bears S. 31° E., 66 lks. dist., with scribe marks  $\frac{1}{2}$  S BT visible on bark blaze.

and bearing trees mkd. by Byron

A fir, 12 ins. diam., bears N. 40° E., 30 lks. dist., with healed blaze.

A fir, 10 ins. diam., bears S. 74° W., 45 lks. dist., with healed blaze.

At the corner point

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap mkd.

T 27 S R 4 W  
 $\frac{1}{2}$   $\frac{S 15}{S 22}$   
1975.

Reset iron pipe alongside iron post.

From the same point, a local corner established by James W. Byron, County Surveyor, in 1959, bears N. 2° 38' W., 0.60 chs. dist., monumented with an iron post, 2 ins. diam., firmly set, protruding 8 ins. above ground, with brass cap mkd.

T 27 S R 4 W  
 $\frac{S 15}{S 22}$  |  $\frac{S 14}{S 23}$   
1959

from which bearing trees mkd. by Byron

A cedar, 38 ins. diam., bears N. 9° E., 116 lks. dist., with healed blaze.

A cedar, 45 ins. diam., bears N. 43° E., 80 lks. dist., with healed blaze.

An oak, 36 ins. diam., bears S. 89° E., 206 lks. dist., with healed blaze.

Land, mountainous, with rolling hills.

Soil, rocky clay.

Timber, fir, cedar, hemlock, pine, yew, maple, live oak, chinquapin, oak, and madrone; undergrowth, vine maple, hazel, manzanita, salal, huckleberry, Oregon grape, and fern.

From the cor. of secs. 14 and 23 only, hereinbefore described.

S. 89° 26' W., bet. secs. 14 and 23.

Ascend 155 ft. over broken NE. slope.

6.90 Dirt road, 15 lks. wide, bears N. 55° W. and S. 55° E.