

Dependent Resurvey of a Portion of the South Boundary,
T. 29 S., R. 7 W., Willamette Meridian, Oregon

CHAINS

T 29 S R 7 W
S 33 | S 34
1924

from which the remains of the original bearing trees

A madrone, 38 ins. diam., bears N. 55° E., 55 lks. dist., no marks visible on decayed blaze.

A root hole, bears S. 66° E., 128 lks. dist.

A root hole, bears S. 48° W., 44 lks. dist., with a down black oak alongside, 16 ins. diam., no marks visible.

and bearing trees mkd. by Mensch

A pine, 17 ins. diam., bears N. 80° E., 93 lks. dist., with healed double blaze.

A fir, 17 ins. diam., bears N. 60° W., 93 lks. dist., with healed double blaze.

Land, mountainous.

Soil, rocky clay loam.

Timber, fir, pine, hemlock, cedar, maple, madrone, alder, chinquapin, and oak; undergrowth, manzanita, Oregon grape, salal, rhododendron, arrowwood, poison oak, blackberry, and fern.

S. 89° 43' W., along the S. bdy. of sec. 33, T. 29 S., R. 7 W.

Ascend 35 ft. along S. slope, through moderate timber and undergrowth.

2.50 Spur, slopes S. 15° W.; desc. 85 ft. over SW. slope.

9.80 Ravine, drains S. 30° E.; asc. 135 ft. over NE. slope.

16.45 Ridge, bears N. 35° W. and S. 35° E.; desc. 110 ft. over broken SW. slope.

28.35 Bottom of descent, slopes N. 20° W.; asc. 10 ft. over E. slope.

30.50 The $\frac{1}{4}$ sec. cor. of sec. 33 only, on the N. bdy. of T. 29 $\frac{1}{2}$ S., R. 7 W., monumented with an iron post, 1 in. diam., firmly set, projecting 6 ins. above ground, with brass cap mkd.

$\frac{1}{4}$ S 33
T 29 $\frac{1}{2}$
1924

from which the remains of the original bearing trees

A decayed fir stump, 6 ins. diam., bears S. 84° E., 12 lks. dist., with scribe marks $\frac{1}{4}$ S33 T29 $\frac{1}{2}$ BT visible on open blaze.

A root hole, bears S. 58° W., 20 lks. dist., with a down fir alongside, 10 ins. diam., with healed blaze.

and bearing trees mkd. by James W. Byron, Deputy County Surveyor, in 1962