

15866

Dependent Resurvey, Portion of Subdivisional Lines,
T. 29 S., R. 4 W., Willamette Meridian, Oregon

CHAINS

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

E 1/16 $\frac{S\ 13}{S\ 24}$
1967

from which a new bearing tree

A yew, 10 ins. diam., bears S. 25° E., 28 lks. dist., mkd. E 1/16 S24 BT.

Reset iron pipe alongside iron post.

S. 46° 48' W., beginning new measurement.

Descend 70 ft. over SW. slope.

4.35 Wet ravine, drains S.; asc. 115 ft. over SE. slope.

15.00 Spur, slopes S. 10° W.; desc. 30 ft. over NW. slope.

17.58 The ¼ sec. cor. of secs. 13 and 24, perpetuated and recorded by M. B. Germond, Deputy County Surveyor, in 1908, and again recorded by F. C. Frear, Deputy County Surveyor in 1918, from original bearing trees which are no longer in existence, and further perpetuated and recorded by James W. Byron, Deputy County Surveyor, in 1960. This cor. is accepted as the best available evidence of the original corner position, monumented with an iron post, 1½ ins. diam., firmly set, projecting 14 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 29 S R 4 W

¼ $\frac{S\ 13}{S\ 24}$

1960

from which the remains of bearing trees mkd. in 1908

A root hole, bears N. 11½° E., 24 lks. dist., with a down fir stump alongside, 15 ins. diam., no marks visible.

A cedar stump, 7 ins. diam., bears S. 44½° W., 22½ lks. dist., with illegible scribe marks visible on partially healed blaze. (Rescribed ¼ S24 CS BT by Byron, in 1960.

and the remains of a bearing tree mkd. by Byron, in 1960

A root hole, bears N. 24° W., 28½ lks. dist., with a down fir alongside, 13 ins. diam., with scribe marks ¼ S13 CS BT visible on open blaze.

and the remains of bearing trees mkd. by Byron, in 1962

A fir snag, 15 ins. diam., bears N. 59° W., 41 lks. dist., with scribe marks ¼ S13 CS BT visible on open blaze.

A cedar, 10 ins. diam., bears S. 22½° W., 74½ lks. dist., with scribe marks ¼ S24 CS BT visible on partially healed blaze.