

Dependent Resurvey, Portion of Subdivisional Lines,
T. 29 S., R. 4 W., Willamette Meridian, Oregon

CHAINS

and a new bearing tree

A cedar, 42 ins. diam., bears N. 37° W., 95 lks.
dist., mkd. $\frac{1}{4}$ S13 BT.

Corner is located at the cor. of wire fences extending
S. 11° W. and N. 89° W.

N. 89° 17' W., beginning new measurement.

Descend 50 ft. over W. slope, along wire fence.

2.00 Ravine, drains S. 15° W.; asc. 60 ft. over SE. slope.

7.00 Spur, slopes S.; desc. 310 ft. over W. slope, changing
to SW. slope.

18.10 Abandoned dirt road, 10 lks. wide, bears N. 20° E. and
S. 20° W.

18.55 Creek, 3 lks. wide, course S. 15° W.; asc. 10 ft. over
SW. slope.

18.89 Point for the W 1/16 sec. cor. of secs. 13 and 24.

Set a fiberglass post, 28 ins. long, 2½ ins. diam., 24
ins. in the ground, with brass cap mkd.

W 1/16 $\frac{S\ 13}{S\ 24}$
1967

from which

A fir, 10 ins. diam., bears N. 65° W., 27 lks.
dist., mkd. W 1/16 S13 BT.

A fir, 7 ins. diam., bears S. 56½° W., 30½ lks.
dist., mkd. W 1/16 S24 BT.

Corner is located alongside a wire fence extending E.
and W.

Ascend 100 ft. over SE. slope.

23.40 Top of ascent, slopes S.; desc. 30 ft. over SW. slope.

26.00 Bottom of descent, slopes S.; asc. 120 ft. over SE.
slope.

31.10 Spur, slopes S.; desc. 75 ft. over SW. slope.

34.25 Bottom of descent, drains S. 10° W.; asc. 90 ft. over
SE. slope.

37.78 The cor. of secs. 13, 14, 23, and 24.

Land, mountainous.

Soil, rocky clay.

Timber, fir, oak, cedar, madrone, maple, yew, dogwood,
cascara, and alder; undergrowth, salal, poison oak, vine
maple, Oregon grape, and blackberry.