

Dependent Resurvey, Portion of Subdivisional Lines,
T. 29 S., R. 4 W., Willamette Meridian, Oregon

CHAINS

Land, mountainous.
Soil, rocky clay.
Timber, fir, oak, cedar, madrone, yew, maple, dogwood,
chinquapin, and cascara; undergrowth, fern, salal, poison
oak, vine maple, Oregon grape, blackberry, thimbleberry,
and hazel.

From the $\frac{1}{4}$ sec. cor. of secs. 10 and 15, perpetuated and
recorded by John H. Markham, Jr., Registered Engineer
No. 2880, in 1956, from evidence no longer in existence,
and further perpetuated and recorded by James W. Byron,
Deputy County Surveyor, in 1963. This corner is accepted
as the best available evidence of the original corner
position, monumented with an iron post, $1\frac{1}{2}$ ins. diam.,
firmly set, projecting 14 ins. above ground, with brass
cap mkd.

T 29 S R 4 W

$\frac{1}{4}$ $\frac{S 10}{S 15}$

1963

from which the remains of bearing trees mkd. by Markham

A cedar, 30 ins. diam., bears East, 171 lks. dist.,
with scribe marks S $\frac{1}{4}$ visible on partially
healed blaze.

A fir stump, 30 ins. diam., bears S. 36° W., 11
lks. dist., with scribe mark T visible on
bark blaze.

A fir, 18 ins. diam., bears S. $48\frac{1}{4}^\circ$ W., 83 lks.
dist., with healed blaze.

A maple stump, 20 ins. diam., bears N. $42\frac{1}{4}^\circ$ W.,
170 lks. dist., with scribe marks BT visible
on open blaze.

and a bearing tree mkd. by Byron

A fir, 13 ins. diam., bears S. $49\frac{1}{4}^\circ$ W., 73 lks.
dist., with healed blaze.

S. $89^\circ 58'$ W., bet. secs. 10 and 15.

Descend 20 ft. over SW. slope, through old logged area
and heavy reproduction.

1.80 Ben Branch Creek, 5 lks. wide, course S. 15° E.; asc.
435 ft. over SE. slope.

15.00 Spur, slopes N. 60° E., also cor. of timber, edges
extend S. and W.; asc. 45 ft. over NE. slope.

18.28 Point for the W $\frac{1}{16}$ sec. cor. of secs. 10 and 15.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins.
in the ground, with brass cap mkd.

W $\frac{1}{16}$ $\frac{S 10}{S 15}$

1969

from which