

15882

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 29 S., R. 4 W., Willamette Meridian, Oregon

## CHAINS

A decayed pine stump, 13 ins. diam., bears  
S. 18° E., 400 lks. dist., no marks visible.

and a bearing tree mkd. by Wood

A fir, 25 ins. diam., bears S. 66½° E., 33½ lks.  
dist., with healed blaze.

and bearing trees mkd. by James W. Byron, Deputy County  
Surveyor, in 1963

A white oak, 9 ins. diam., bears N. 34½° E., 58  
lks. dist., with healed double blaze.

A pine, 10 ins. diam., bears S. 49½° W., 61 lks.  
dist., with healed double blaze.

A cedar, 16 ins. diam., bears N. 48¼° W., 85 lks.  
dist., with healed double blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins.  
in the ground, with brass cap mkd.

*FO. OK 8/93  
B. SHAWER R.M. 3-79*

T 29 S R 4 W  
S 17 | S 16  
S 20 | S 21  
1969

Reset iron pipe alongside iron post.

Corner is located in a fence cor., with fences extending  
N. and E.

Land, mountainous and bottom land.

Soil, rocky clay loam.

Timber, fir, oak, cedar, madrone, yew, maple, dogwood,  
pine, chinquapin, and cascara; undergrowth, fern, salal,  
poison oak, vine maple, Oregon grape, blackberry, hazel,  
and thimbleberry.

From the cor. of secs. 15, 16, 21, and 22.

N. 87° 45' W., bet. secs. 16 and 21.

Descend 100 ft. over SW. slope, through old logged area  
and heavy reproduction.

5.30 Creek, 2 lks. wide, course S. 20° W.; asc. 125 ft. over  
SE. slope.

7.65 Dirt road, 15 lks. wide, bears NE. and SW.

12.25 Spur, slopes S. 15° E.; asc. 30 ft. over SE. slope,

15.87 Intersect the E. bdy. of Donation Land Claim No. 39,  
and point for the crossing closing corner.

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins.  
in the ground, with brass cap mkd.

*FO. OK 8/93  
B. SHAWER R.M. 3-79*

T 29 S R 4 W  
C 39 | S 16 CCC  
S 21  
1969