

Dependent Resurvey of Donation Land Claim No. 38,
T. 29 S., R. 4 W., Willamette Meridian, Oregon

CHAINS	
	A cedar, 14 ins. diam., bears S. $64\frac{1}{2}^{\circ}$ W., 632 lks. dist., mkd. C38 BT.
	A pine, 23 ins. diam., bears S. $70\frac{1}{4}^{\circ}$ W., 597 lks. dist., mkd. C38 BT.
	N. $89^{\circ} 51'$ W., along the N. bdy. of Claim No. 38.
	Descend 15 ft. over SW. slope, through open field.
5.80	Louis Creek, 15 lks. wide, course S. 5° E.; asc. 30 ft. over rolling SE. slope.
12.10	Wire fence, extends N. 20° W. and S. 20° E.
14.10	Creek, 1 lks. wide, course S. 25° E.; asc. 160 ft. over rolling SE. slope.
15.00	Wire fence, extends N. 70° W. and S. 70° E.
31.50	Corner of fences, with fences extending N. 80° E., W., and S., also enter heavy timber and dense undergrowth, edge bears N. and S.
34.20	Dirt road, 15 lks. wide, bears N. 20° E. and S. 20° W.
35.70	Spur, slopes S. 10° E.; desc. 20 ft. over SW. slope.
38.00	Ravine, drains S. 10° E.; asc. 40 ft. over SE. slope.
41.20	Spur, slopes S. 20° W.; desc. 175 ft. over SW. slope.
49.10	Gravelled road, 20 lks. wide, bears N. and S.
50.50	Ben Branch Creek, 5 lks. wide, course S. 5° E.; asc. 190 ft. over SE. slope.
57.90	Spur, slopes S. 25° E.; desc. 55 ft. over SW. slope.
63.50	Ravine, drains S. 20° E.; asc. 95 ft. over SE. slope.
69.00	Spur, slopes S.; desc. 120 ft. over SW. slope.
78.70	Draw, drains S.; asc. 90 ft. over SE. slope.
83.80	Spur, slopes S.; desc. 125 ft. over SW. slope.
94.35	Dry bed of creek, drains S. 10° W.; asc. 75 ft. over SE. slope.
101.55	Spur, slopes S.; desc. 25 ft. over broken SW. slope.
104.46	The crossing closing cor. of secs. 21 and 22, at intersection with the N. bdy. of Claim No. 38, hereinbefore described.
	From this point, the cor. of secs. 15, 16, 21, and 22, bears N. $1^{\circ} 10'$ E., 9.43 chs. dist.
	Ascend 5 ft. over broken ground.
105.80	Spur, slopes S.; desc. 130 ft. over W. slope.
111.80	Creek, 2 lks. wide, course S.; asc. 110 ft. over SE. slope.
111.95	Fence, extends N., E., and S.