

16046

Dependent Resurvey, Portion of Subdivisional Lines,
T. 22 S., R. 9 W., Willamette Meridian, Oregon

CHAINS
79.32

The cor. of secs. 21, 22, 27, and 28, monumented with the original sandstone, 20 x 14 x 6 ins., firmly set 10 ins. in the ground, mkd. with 3 grooves on E. and 2 grooves on S. faces, from which the remains of an original bearing tree:

A decayed fir stump, size indeterminate, bears N. 22° E., 8 lks. dist., no marks visible.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd.

T 22 S R 9 W
S 21 | S 22
S 28 | S 27
1975

from which new bearing trees

A maple, 22 ins. diam., bears N. 28½° E., 66 lks. dist., mkd. T22S R9W S22 BT.

A fir, 27 ins. diam., bears S. 37¾° E., 60 lks. dist., mkd. T22S R9W S27 BT.

A fir, 18 ins. diam., bears S. 47½° W., 15 lks. dist., mkd. T22S R9W S28 BT.

A fir, 30 ins. diam., bears N. 29½° W., 83 lks. dist., mkd. T22S R9W S21 BT.

Deposit corner stone alongside iron post.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock, cedar, alder, maple, and cherry; undergrowth, blackberry, salmonberry, poison oak, vine maple, fern, Oregon grape, salal, huckleberry, and hazel.

S. 0° 41' E., bet. secs. 27 and 28.

Ascend 50 ft. along E. slope, through moderate timber and undergrowth.

1.90 Top of ascent, slopes NE.; desc. 60 ft. over S. slope.

3.60 Creek, 3 lks. wide, course N. 75° E.; asc. 160 ft. over steep N. slope.

12.30 Spur, slopes N. 40° E.; desc. 190 ft. over S. slope.

19.40 Creek, 5 lks. wide, course N. 40° E.; asc. 200 ft. over N. slope.

31.90 Ravine, drains N. 15° E.; asc. 180 ft. over N. slope.

38.85 The ¼ sec. cor. of secs. 27 and 28, monumented with the original sandstone, 12 x 10 x 6 ins., loosely set on top of ground, mkd. ¼ on top, from which the remains of the original bearing trees:

A fir snag, 36 ins. diam., bears N. 17° E., 20 lks. dist., no marks visible.