

16064

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 22 S., R. 9 W., Willamette Meridian, Oregon

CHAINS

and bearing trees mkd. by the County Surveyor

A fir, 8½ ins. diam., bears S. 26° E., 27 lks.  
dist., with healed blaze.

A fir, 15 ins. diam., bears S. 61° W., 16 lks.  
dist., with healed blaze.

Add marks AM 1974 to brass cap.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock, cedar, oak, maple, and alder;  
undergrowth, fern, vine maple, salal, Oregon grape,  
poison oak, blackberry, thimbleberry, and rhododendron.

The following field notes describe the remonumentation of a certain original corner point, township 22 south, range 9 west, Willamette Meridian, Oregon, as provided for in the Special Instructions, Group Number 1000, Oregon, dated July 13, 1979, "Investigation of Physical Evidence of Corner Positions and Accessories, Followed by Remonumentation of Corner Points, with New Accessories when Needed".

The remonumentation of this certain original corner point was made at the request of the Coos Bay District Manager, for administrative purposes of the Bureau of Land Management.

Subdivisions, T. 22 S., R. 9 W.,  
Willamette Meridian, Oregon

(Remonumenting a corner established by William H. Byars,  
U. S. Deputy Surveyor, in 1874)

The ¼ sec. cor. of secs. 24 and 25, perpetuated by person (s) unknown, monumented with a wooden stake, 4 x 4 x 36 ins., firmly set 18 ins. in the ground, in the root hole of the original corner tree, lying alongside, a fir, 40 ins. diam., with scribe marks 1 S visible on open blaze on one side and healed blaze on opposite side.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap mkd.

T 22 S R 9 W  
¼ S 24  
S 25  
1979

from which

A fir, 6 ins. diam., bears N. 29° W., 12 lks.  
dist., mkd. ¼ S24 BT.

An alder, 7 ins. diam., bears S. 57½° E., 5 lks.  
dist., mkd. ¼ S25 BT.

Reset wooden stake alongside iron post.