

303

Dependent Resurvey of a Portion of the West Boundary,
T. 20 S., R. 6 W., Willamette Meridian, Oregon

CHAINS

A fir, 68 ins. diam., bears S. 82° W., 35 lks. dist., with scribe marks T20S R6W visible on open blaze.

and the remains of bearing trees mkd. by Godfrey

A hemlock, 15 ins. diam., bears N. 40° E., 187 lks. dist., with healed blaze.

A hemlock snag, 16 ins. diam., bears S. 76° E., 156 lks. dist., with scribe marks R6W S19 RCS BT visible on open blaze.

and bearing trees mkd. by Wayne R. Tinglum, Engineering Technician for Bureau of Land Management, in 1976

A fir, 5 ins. diam., bears N. 0½° E., 18 lks. dist., with scribe marks T20S R6W S18 BT visible on open blaze.

A fir, 5 ins. diam., bears S. 32¾° E., 14½ lks. dist., with scribe marks T20S R6W S19 BT visible on open blaze.

Set a 5 ft. steel fence post alongside iron post.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock, cedar, yew, maple, alder, madrone, chinquapin, and dogwood; undergrowth, vine maple, hazel, arrowwood, huckleberry, Oregon grape, salal, and fern.

N. 10° 53' E., bet. secs. 13 and 18.

Ascend 90 ft. over SW. slope, through heavy timber and dense undergrowth.

5.60 Spur, slopes W.; desc. 150 ft. over NW. slope.

7.80 Dry creek bed, 3 lks. wide, course N. 60° W.; asc. 5 ft. along W. slope.

29.20 Panther Creek, 10 lks. wide, course S. 75° W.; asc. 80 ft. over SW. slope.

30.50 Gravelled road, 25 lks. wide, bears N. 75° E. and S. 75° W.

42.30 Spur, slopes W.; desc. 10 ft. over NW. slope.

43.97 The ¼ sec. cor. of secs. 13 and 18, reestablished at proportionate distance by John D. Venator, Registered Land Surveyor No. 278, in 1954, monumented with a steel steering gear shaft, 1 in. diam., firmly set, projecting 4 ins. above ground. There is no remaining evidence of the original corner; therefore, this point is accepted as the best available evidence of the position of the original corner, from which the remains of the bearing trees mkd. by Venator:

A root hole, bears S. 33° E., 28 lks. dist., with a down and decayed hemlock alongside, 12 ins. diam., no marks visible.

A root hole, bears S. 47° W., 40 lks. dist., with a down and decayed hemlock alongside, 18 ins. diam., no marks visible.