

16075

Dependent Resurvey of a Portion of the West Boundary,
T. 20 S., R. 6 W., Willamette Meridian, Oregon

CHAINS

and the remains of bearing trees mkd. by Lyle E. Boustead
Land Agent for Weyerhaeuser Timber Company, in 1959

A fir snag, 12 ins. diam., bears N. 1° E., 99 lks.
dist., no marks visible.

A fir snag, 25 ins. diam., bears S. 13° E., 17½
lks. dist., with a galvanized nail with "W"
embossed on head, at base.

A root hole, bears S. 54° W., 39 lks. dist., with
a down fir alongside, 24 ins. diam., no marks
visible.

At the corner point

Remove the 1949 iron post and in its place, set an iron
post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground,
with brass cap mkd.

T 19 S
R 7 W R 6 W
S 36 S 31
S 1 S 6
R 6½ W R 6 W
T 20 S
1978

No suitable trees available within limits.

Set a 5 ft. steel fence post alongside iron post.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock, cedar, maple, alder, chinquapin,
and dogwood; undergrowth, manzanita, vine maple, hazel,
arrowwood, huckleberry, Oregon grape, salal, wild rose,
blackberry, and fern.

Dependent Resurvey of a Portion of the South Boundary,
T. 19 S., R. 7 W., Willamette Meridian, Oregon

(Restoring the survey by Henry C. and Joseph Perkins,
U. S. Deputy Surveyors, in 1874,
and the resurvey by Norman D. Price and
Thomas A. Tillman, Cadastral Engineers, in 1949)

From the cor. of Tps. 19 and 20 S., Rs. 6, 6½, and 7 W.

S. 89° 49' W., on the S. bdy. of sec. 36, marking and
blazing the true line.

Descend 15 ft. along broken S. slope, across logged area
through moderate undergrowth.

- | | |
|-------|---|
| 1.80 | Spur, slopes SW.; desc. 60 ft. over broken SW. slope. |
| 3.85 | Creek, 1 lk. wide, course S. 15° W.; asc. 60 ft. over
SE. slope. |
| 7.60 | Top of ascent, slopes S.; desc. 20 ft. along broken S.
slope. |
| 10.05 | Spur, slopes SW.; desc. 70 ft. over broken SW. slope. |