

Dependent Resurvey of a Portion of the South Boundary,
T. 19 S., R. 7 W., Willamette Meridian, Oregon

CHAINS	
6.45	Left bank Siuslaw River, bears N. 30° E. and S. 30° W., course S. 30° W.; thence across river.
8.00	Right bank Siuslaw River, bears N. 30° E. and S. 30° W.; asc. 40 ft. over SE. slope.
11.58	True point for the closing cor. of secs. 2 and 3, T. 20 S., R. 7 W., hereinafter described. Ascend 40 ft. over SE. slope.
25.30	Top of broad spur, slopes S., also dirt road, 10 lks. wide, bears N. 15° E. and S. 30° W., in curve; desc. 85 ft. over NW. slope.
27.40	Right bank Siuslaw River, bears N. 15° E. and S. 15° W., course N. 15° E.; thence across river.
28.50	Left bank Siuslaw River, bears N. 15° E. and S. 15° W.; asc. 20 ft. across bottom land.
40.68	The ¼ sec. cor. of sec. 34 only, monumented with an iron post, 1 in. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd.
	$\frac{1}{4} S 34$ 1949
	from which the remains of an original bearing tree
	A white fir snag, 36 ins. diam., bears S. 10° E., 30 lks. dist., no marks visible.
	and bearing trees mkd. by Price and Tillman
	A hemlock, 35 ins. diam., bears N. 72° E., 47 lks. dist., with scribe marks ¼ S34 BT visible on open blaze.
	A fir, 78 ins. diam., bears N. 53¼° W., 18 lks. dist., with healed blaze.
	Set a 5 ft. steel fence post alongside iron post.
	<hr style="width: 20%; margin: auto;"/>
	N. 89° 20' W., beginning new measurement.
	Ascend 75 ft. over broken S. slope.
9.90	Point for the ¼ sec. cor. of sec. 3 only, T. 20 S., R. 7 W., at midpoint on the N. bdy. of sec. 3.
	Set an iron post, 28 ins. long, 2½ ins. diam., 20 ins. in the ground, with brass cap mkd.
	$\begin{array}{c} T 19 S R 7 W \\ \frac{1}{4} S 3 \\ T 20 S R 7 W \\ 1977 \end{array}$
	from which
	A cedar, 13 ins. diam., bears S. 32° E., 23 lks. dist., mkd. ¼ S3 BT.
	A fir, 59 ins. diam., bears S. 46½° W., 72 lks. dist., mkd. ¼ S3 BT.