

Dependent Resurvey, Portion of Subdivisional Lines,
T. 20 S., R. 7 W., Willamette Meridian, Oregon

CHAINS	
6.60	Ridge, bears N. 30° W. and S. 30° E.; desc. 655 ft. over broken SW. slope.
6.90	Gravelled road, 25 lks. wide, bears N. 30° W. and S. 30° E., also enter Oxbow Burn, edge bears same as road.
37.20	Creek, 3 lks. wide, course S. 40° W.; desc. 15 ft. along S. slope, changing to SW. slope.
39.61	The cor. of secs. 2, 3, 10, and 11.
	Land, mountainous. Soil, rocky clay. Timber, fir, hemlock, cedar, yew, maple, alder, dogwood, chinquapin, and madrone; undergrowth, vine maple, willow, arrowwood, hazel, manzanita, ceanothus, blackberry, Oregon grape, salal, and fern.
	N. 0° 09' E., bet. secs. 2 and 3.
	Ascend 200 ft. over SW. slope, changing to W. slope, through scattered timber and dense undergrowth, across Oxbow Burn.
18.60	Spur, slopes N. 75° W.; desc. 90 ft. over NW. slope.
24.00	Ravine, drains SW.; asc. 260 ft. over SE. slope.
31.10	Spur, slopes S. 35° W.; asc. 65 ft. along W. slope.
39.36	The 1/4 sec. cor. of secs. 2 and 3, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd.
	$\frac{1}{4}$ S 3 S 2 T 20 S R 7 W 1967
	from which the remains of the original bearing trees
	A sawed fir stump, 35 ins. diam., bears N. 29° E., 50 lks. dist., with healed blaze.
	A root hole, bears S. 46° W., 27 lks. dist., with a down fir alongside, 50 ins. diam., with healed blaze.
	and the remains of a bearing tree mkd. by Glenn and Roseberry.
	A down fir, 10 ins. diam., bears N. 21° W., 159 lks. dist., with scribe marks S3 BT visible on partially healed blaze. The standing position of this tree cannot be determined. (Record, N. 24 1/2° W., 162 lks.)
	No suitable trees available within limits.
	Set a 5 ft. steel fence post alongside iron post.
	N. 0° 19' E., beginning new measurement.
	Ascend slightly along W. slope.