

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 23 S., R. 4 W., Willamette Meridian, Oregon

CHAINS

A fir, 8 ins. diam., bears S. 75° W., 8½ lks.  
dist., with healed blaze.

A fir, 9 ins. diam., bears N. 49° W., 19 lks.  
dist., with healed blaze.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock, cedar, maple, oak, madrone, alder,  
chinquapin, and myrtle; undergrowth, salal, vine maple,  
poison oak, rhododendron, hazel, Oregon grape, and fern.

From the cor. of secs. 13, 14, 23, and 24, monumented  
with an iron post, 2½ ins. diam., firmly set, projecting  
4 ins. above ground, with brass cap mkd.

T 23 S R 4 W  
S 14 | S 13  
S 23 | S 24  
1971

from which the remains of bearing trees mkd. by Wilford  
Haines, Registered Land Surveyor No. 239, in 1963, and  
described by James E. Jelley, in 1971

A fir, 24 ins. diam., bears N. 9½° E., 57½ lks.  
dist., with healed blaze. (Record, N. 12° E.)

A sawed fir stump, 26 ins. diam., bears S. 17½° E.,  
42½ lks. dist., with healed blaze. (Record,  
S. 21° E.)

A fir, 23 ins. diam., bears S. 55° W., 95½ lks.  
dist., with healed blaze. (Record, S. 58° W.)

A fir, 13 ins. diam., bears N. 74½° W., 13 lks.  
dist., with healed blaze. (Record, N. 72½° W.)

N. 89° 45' W., bet. secs. 14 and 23.

Descend 15 ft. over NW. slope, through heavy timber and  
dense undergrowth.

2.85 Creek, 1 lk. wide, course N. 25° W.; asc. 5 ft. over  
NE. slope.

3.40 Spur, slopes N. 50° W.; desc. 45 ft. over broken NW.  
slope.

6.25 Creek, 1 lk. wide, course N. 50° W.; asc. 165 ft. over  
NE. slope.

16.40 Ridge, bears N. 15° E. and S. 40° W.; desc. 50 ft. over  
NW. slope.

19.76 Point for the E 1/16 sec. cor. of secs. 14 and 23.

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins.  
in the ground, with brass cap mkd.

E 1/16 S 14  
S 23  
1976

from which