

Dependent Resurvey, Portion of Subdivisional Lines,
T. 23 S., R. 4 W., Willamette Meridian, Oregon

CHAINS

and the remains of a bearing tree mkd. by Byron

A root hole, bears S. $41\frac{1}{2}^{\circ}$ E., 70 lks. dist., with
a down fir alongside, 18 ins. diam., with
fragmentary scribe marks visible on open blaze.

and bearing trees mkd. by Tracy

A fir, 24 ins. diam., bears N. $5\frac{1}{2}^{\circ}$ W., $41\frac{1}{2}$ lks.
dist., with healed blaze.

A maple, 24 ins. diam., bears S. $26\frac{1}{2}^{\circ}$ W., 52 lks.
dist., with scribe marks $\frac{1}{4}$ S34 CS BT visible
on open blaze.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins.
in the ground, with brass cap mkd.

FD 1/95
M 121-69

$\frac{1}{4}$ S 27
S 34
T 23 S R 4 W
1976

Reset "T" shaped iron rod alongside iron post.

S. $88^{\circ} 39'$ W., beginning new measurement.

Descend 185 ft. over NW. slope.

- 9.30 Ravine, drains N. 45° W.; asc. 55 ft. over NE. slope.
10.90 Spur, slopes N. 45° E.; desc. 285 ft. over NW. slope.
31.25 Creek, 2 lks. wide, course S.; asc. 30 ft. over SE.
slope.
33.10 Spur, slopes S. 30° E.; desc. 60 ft. over SW. slope.
39.84 The cor. of secs. 27, 28, 33, and 34.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock, cedar, maple, oak, myrtle, madrone,
and chinquapin; undergrowth, salal, rhododendron, hazel,
Oregon grape, poison oak, vine maple, and fern.

N. $1^{\circ} 22'$ E., bet. secs. 27 and 28.

Ascend 275 ft. over SW. slope, through heavy timber and
dense undergrowth.

- 1.40 Gravelled road, 30 lks. wide, bears N. 80° W. and
S. 80° E.
14.10 Spur, slopes N. 65° W.; desc. 70 ft. over broken NW.
slope.
24.55 Ravine, drains S. 50° W.; asc. 80 ft. over SW. slope.
28.35 Ridge, bears N. 60° E. and S. 60° W.; desc. 100 ft. over
broken NW. slope, changing to NE. slope.