

Dependent Resurvey of a Portion of the South Boundary,
T. 31 S., R. 8 W., Willamette Meridian, Oregon

<p>CHAINS 73.15</p>	<p>Spur, slopes S. 55° W.; desc. 100 ft. over W. slope.</p>
<p>76.42</p>	<p>Point for the cor. of secs. 1, 2, 35, and 36, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center;"> <p>T 31 S R 8 W S 35 S 36 S 2 S 1 T 32 S 1977</p> </div> <p>from which</p> <p>A fir, 7 ins. diam., bears N. 17° E., 66 lks. dist., mkd. T31S R8W S36 BT.</p> <p>A fir, 6 ins. diam., bears S. 35½° E., 47 lks. dist., mkd, T32S R8W S1 BT.</p> <p>A fir, 14 ins. diam., bears S. 51½° W., 42 lks. dist., mkd. T32S R8W S2 BT.</p> <p>A fir, 5 ins. diam., bears N. 22½° W., 35 lks. dist., mkd. T31S R8W S35 BT.</p> <p>Land, mountainous. Soil, rocky clay. Timber, fir, hemlock, cedar, maple, oak, live oak, myrtle, chinquapin, and alder; undergrowth, salal, poison oak, Oregon grape, rhododendron, vine maple, and fern.</p>
<p>18.90</p>	<p>N. 89° 51' W., bet. secs. 2 and 35.</p> <p>Descend 620 ft. over steep W. slope, through heavy timber and dense undergrowth.</p> <p>Ravine, drains S. 60° W.; asc. 45 ft. over SE. slope.</p>
<p>19.105</p>	<p>Point for the E 1/16 sec. cor. of secs. 2 and 35.</p> <p>Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center;"> <p>T 31 S R 8 W E 1/16 S 35 S 2 T 32 S 1977</p> </div> <p>from which</p> <p>A pine, 6 ins. diam., bears N. 32½° E., 20½ lks. dist., mkd. E 1/16 S35 BT.</p> <p>A fir, 7 ins. diam., bears S. 57° E., 38 lks. dist., mkd. E 1/16 S2 BT.</p> <p>Corner is located at top of ascent, slopes S.; desc. 110 ft. over broken SW. slope.</p>
<p>26.65</p>	<p>Ravine, drains S. 20° W.; asc. 145 ft. over SE. slope.</p>

*FD OK
9/20/13
CS 65/80-19
L. Quimby*