

18261

Corrective Dependent Resurvey of a Portion of
the North Boundary,
T. 31 S., R. 7 W., Willamette Meridian, Oregon

CHAINS
78.25

Same dirt road, 15 lks. wide, bears S. 85° E. and S. 85° W., in curve.

81.48

The cor. of secs. 2, 3, 34, and 35, perpetuated and recorded by James W. Byron, County Surveyor, in 1962, monumented with an iron post, 1 in. diam., firmly set, projecting 14 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

S 34 | S 35 R

S 3 | S 2 7

T 31 S W

1962

from which the remains of the original bearing trees

A pine snag, 37 ins. diam., bears N. 65½° E., 217 lks. dist., no marks visible.

A pine, 25 ins. diam., bears S. 87½° W., 32 lks. dist., with fragmentary scribe marks visible on open blaze.

and bearing trees mkd. by Byron

A cedar, 24 ins. diam., bears N. 32° E., 19 lks. dist., with scribe marks T30S R7W S35 CS BT visible on open blaze.

A pine, 13 ins. diam., bears S. 27° E., 13 lks. dist., with scribe marks T31S R7W S2 CS BT visible on open blaze.

A pine, 10 ins. diam., bears N. 1½° W., 71 lks. dist., with scribe marks 31 CS visible on open blaze.

Land, mountainous.

Soil, rocky clay loam.

Timber, fir, hemlock, cedar, maple, oak, madrone, myrtle, chinquapin, and alder; undergrowth, salal, rhododendron, vine maple, poison oak, Oregon grape, and fern.

Corrective Dependent Resurvey of a Portion of
the Subdivisional Lines,
T. 31 S., R. 7 W., Willamette Meridian, Oregon

(Restoring the survey by William H. Byars,
U. S. Deputy Surveyor, in 1872,
and correcting the resurvey by James E. Jelley,
Cadastral Surveyor, in 1969)

From the cor. of secs. 1, 2, 11, and 12, monumented with an iron post, 2½ ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd.

T 31 S R 7 W

S 2 | S 1

S 11 | S 12

1969

from which the remains of the original bearing trees