

Dependent Resurvey of a Portion of the West Boundary,
T. 19 S., R. 10 W., Willamette Meridian, Oregon

CHAINS	
	<p style="text-align: center;">USDA FOREST SERVICE T 19 S R 11 W R 10 W S 25 S 30 S 36 S 31 1979 PLS 1305</p> <p>from which the remaining original bearing trees</p> <p>An alder, 18 ins. diam., bears N. 74° E., 74 lks. dist., with decayed blaze, no marks visible.</p> <p>A fir, 48 ins. diam., bears S. 41½° E., 129 lks. dist., with healed blaze.</p> <p>and bearing trees mkd. by Prochnau</p> <p>An alder, 12 ins. diam., bears N. 26½° E., 24 lks. dist., with scribe marks T19S R10W S30 BT visible on bark.</p> <p>A fir, 21 ins. diam., bears N. 39° E., 96 lks. dist., with scribe marks T19S R10W S30 BT visible on open blaze.</p> <p>An alder, 16 ins. diam., bears S. 36¼° W., 54 lks. dist., with scribe marks T19S R11W S36 BT visible on bark.</p> <p>A fir, 18 ins. diam., bears N. 9¼° W., 83 lks. dist., with scribe marks T19S R11W S25 BT visible on open blaze.</p> <p>Corner is located 10 lks. south of ravine, drains S. 70° E.</p> <p>Land, mountainous. Soil, sandy clay. Timber, fir, alder, maple, hemlock, cedar, chinquapin, and cascara; undergrowth, young timber, vine maple, salmonberry, salal, rhododendron, huckleberry, blackberry, and fern.</p>
	<p>Dependent Resurvey of a Portion of the Subdivisional Lines T. 19 S., R. 10 W., Willamette Meridian, Oregon</p>
	<p style="text-align: center;">(Restoring the survey by Henry L. Chandler, U. S. Deputy Surveyor, in 1899)</p>
	<p>From the cor. of secs. 5, 6, 31, and 32, on the S. bdy. of the Tp.</p> <p>N. 2° 01' W., bet. secs. 31 and 32, marking and blazing the true line.</p> <p>Ascend 50 ft. over S. slope, through heavy timber and dense undergrowth.</p>
1.10	Spur, slopes S. 75° E.; desc. 170 ft. over broken NE. slope.
9.65	Ravine, drains E.; asc. 160 ft. over S. slope.