

Dependent Resurvey, Portion of Subdivisional Lines,
T. 32 S., R. 6 W., Willamette Meridian, Oregon

CHAINS

Set an iron post, 28 ins. long, 2½ ins. diam., 21 ins. in the ground, directly over iron pipe, with brass cap mkd.

T 32 S R 6 W
¼ S 20
S 29
1976

Land, mountainous.
Soil, rocky clay.

Timber, fir, pine, cedar, yew, hemlock, oak, madrone, and alder; undergrowth, poison oak, manzanita, ceanothus, hazel, salal, Oregon grape, and fir reproduction.

From the cor. of secs. 16, 17, 20, and 21.

S. 88° 42' W., bet. secs. 17 and 20.

Descend 290 ft. over W. slope, changing to SW. slope, through medium timber and dense undergrowth.

10.70 Creek, 2 lks. wide, course NW.; asc. 70 ft. over NE. slope.

16.80 Spur, slopes N.; desc. 40 ft. over NW. slope.

19.20 Bottom of descent, slopes N.; asc. 40 ft. over NE. slope.

22.50 Spur, slopes N. 60° W.; desc. 300 ft. over NW. slope.

32.10 Creek, 2 lks. wide, course N.; asc. 125 ft. over NE. slope.

38.84 The ¼ sec. cor. of secs. 17 and 20, monumented with the remains of the original corner tree, a sawed and decayed fir stump, 24 ins. diam., no marks visible, from which the remains of the original bearing trees:

A decayed fir snag, size indeterminate, bears S. 30° E., 22 lks. dist., with chaining notch visible on decayed blaze.

A root hole, bears N. 10° W., 26 lks. dist., with a down and decayed ponderosa pine alongside, size indeterminate, with illegible scribe marks visible on opened double blaze.

At the corner point

Remove the decayed fir stump and set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 32 S R 6 W
¼ S 17
S 20
1976

from which new bearing trees

A fir, 8 ins. diam., bears N. 51° W., 15 lks. dist., mkd. ¼ S17 BT.

A fir, 7 ins. diam., bears S. 47½° E., 20½ lks. dist., mkd. ¼ S20 BT.