

379

Dependent Resurvey, Portion of Subdivisional Lines,
T. 25 S., R. 1 W., Willamette Meridian, Oregon

CHAINS	
	<p>From the cor. of secs. 28, 29, 32, and 33.</p> <p>S. 88° 49' W., bet. secs. 29 and 32.</p> <p>Descend 30 ft. over SW. slope, through heavy timber and dense undergrowth.</p>
2.15	Ravine, drains S. 15° E.; asc. 425 ft. over SE. slope.
24.60	Ridge, bears N. and S.; desc. 300 ft. over broken SW. slope.
38.65	Ravine, drains S. 10° W.; asc. 15 ft. over SE. slope.
39.15	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 29 and 32, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center;"> <p>T 25 S R 1 W</p> <p>$\frac{1}{4}$ $\frac{S 29}{S 32}$</p> <p>1978</p> </div> <p>from which</p> <p>A fir, 10 ins. diam., bears N. 43° W., $30\frac{1}{2}$ lks. dist., mkd. $\frac{1}{4}$ S29 BT.</p> <p>A fir, 14 ins. diam., bears S. 14$\frac{1}{2}$° E., 9 lks. dist., mkd. $\frac{1}{4}$ S32 BT.</p> <p>Ascend 415 ft. over broken SE. slope.</p>
73.50	Ridge, bears E. and W.; desc. 20 ft. along ridge top.
77.50	Dirt road, 12 lks. wide, bears N. 80° W. and S. 80° E.
78.30	The cor. of secs. 29, 30, 31, and 32.
	<p>Land, mountainous.</p> <p>Soil, rocky clay.</p> <p>Timber, fir, hemlock, cedar, maple, oak, madrone, alder, and chinquapin; undergrowth, salal, Oregon grape, vine maple, rhododendron, poison oak, and fern.</p>
	<p>S. 89° 32' W., bet. secs. 30 and 31.</p> <p>Ascend 145 ft. over broken NE. slope, through heavy timber and dense undergrowth.</p>
11.00	Ridge, bears N. 45° W. and S. 55° E.; desc. 75 ft. over SW. slope.
18.75	Dirt road, 15 lks. wide, bears N. 55° W. and S. 55° E.
26.00	Ravine, drains S. 15° E.; asc. 240 ft. over SW. slope.
33.85	Dirt road, 15 lks. wide, bears N. 55° E. and S. 45° W.
35.75	Spur, slopes N. 50° E.; asc. 60 ft. over NE. slope.
38.45	Spur, slopes N. 65° E.; desc. 10 ft. over NW. slope.