

County Surveyor's Record, Douglas County, Oregon

16392

Dependent Resurvey, Portion of Subdivisional Lines,
T. 24 S. R. 4 W., Willamette Meridian, Oregon

CHAINS

- N. 0° 25' E., beginning new measurement.
- Descend 80 ft. over NW slope.
- 5.05 Creek, 1 lk. wide, course N. 45° E.; desc. 195 ft. over NE slope.
- 12.85 Creek, 1 lk wide, course N. 75° E.; asc. 95 ft. over broken SE slope.
- 25.55 Spur, slopes N. 40° E.; desc. 80 ft. over NE slope.
- 32.85 Spur, slopes N. 30° E.; desc. 215 ft. over NW slope.
- 39.15 Creek, 2 lks. wide, course N. 70° W.; asc. 15 ft. over SE slope.
- 39.85 The cor. of secs. 3, 4, 9, and 10, perpetuated and recorded by James W. Byron, Deputy County Surveyor, in 1961, and further perpetuated and recorded by Milo E. Godfrey, Deputy County Surveyor in 1963, monumented with an iron post, 1 1/4 ins. diam., firmly set, projecting 8 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 24 S R 4 W

S 4	S 3
S 9	S 10

 1961

from which the remains of the original bearing trees

- A cedar stump, 36 ins. diam., bears N. 36 1/2° E., 36 lks. dist., no marks visible.
- A cedar snag, 40 ins. diam., bears S. 88° E., 88 lks. dist., with healed blaze.
- A root hole, bears S. 40° W., 46 lks. dist., with a down hemlock alongside, 20 ins. diam., no marks visible.
- A sawed cedar stump, 40 ins. diam., bears N. 33° W., 54 lks, dist., with fragmentary scribe marks visible on open blaze.

and bearing trees mkd. by Byron

- A hemlock, 11 ins. diam., bears S. 10 1/4° W., 73 1/2 lks. dist., with healed blaze.
- A hemlock, 16 ins. diam., bears N. 78° W., 35 lks. dist., with healed blaze.
- A hemlock, 16 ins. diam., bears N. 1/2° W., 73 1/2 lks., dist., with healed blaze.

and a bearing tree mkd. by Godfrey

- A cedar, 42 ins. diam., bears S. 38° E., 81 lks. dist., with fragmentary scribe marks visible on open blaze.

No suitable tree available within limits in sec. 3.

Land, mountainous.
Soil, rocky clay loam.