

# County Surveyor's Record, Douglas County, Oregon

16405

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 24 S., R. 4 W., Willamette Meridian, Oregon

CHAINS

A madrone, 10 ins. diam., bears S. 81° E., 159 lks. dist., with healed blaze.

A sawed fir stump, 17 ins. diam., bears S. 72° W., 149 lks. dist., with healed blaze.

A sawed fir stump, 15 ins. diam., bears N. 73° W., 125 lks. dist., with healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T 24 S R 4 W  
S 30 | S 29  
S 31 | S 32  
1979

No other suitable trees available within limits.

Deposit corner stone alongside iron post.

Land, mountainous.

Soil, rocky clay loam.

Timber, fir, hemlock, cedar, maple, oak, madrone, alder, chinquapin, and ash; undergrowth, salal, vine maple, poison oak, rhododendron, Oregon grape, and fern.

N 0° 02' W., bet. secs. 29 and 30.

Ascend 55 ft. over SE slope, through open logged area.

12.60 Ridge, bears N. 70° E., and S. 70° W.; desc. 345 ft. over broken N. slope.

38.20 Creek, 2 lks. wide, course N. 65° W.; asc. 55 ft. over SW slope.

40.08 The 1/4 cor. of secs. 29 and 30, perpetuated and recorded by F.C. Frear, Deputy County Surveyor, in 1931, from original evidence no longer in existence, and further perpetuated and recorded by Milo E. Godfrey, Deputy County Surveyor, in 1960-63, monumented with an iron post, 1 1/4 ins. diam., firmly set, projecting 1 in. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 24 S  
1/4 S 30 | S 29  
R 4 W  
1963

*Fd. B.C.  
11/92 M. Heimbauer  
M116-18*

from which the remains of bearing trees mkd. by Godfrey

A sawed fir stump, 10 ins. diam., bears S. 72° E., 95 lks. dist., with healed blaze.

A black oak, 10 ins. diam., bears N. 66° W., 31 1/2 lks. dist., with healed blaze.

A sawed fir stump, 10 ins. diam., bears N. 12° W., 67 1/2 lks. dist., with healed blaze.

and a new reference monument