

County Surveyor's Record, Douglas County, Oregon

16443

Dependent Resurvey, Portion of Subdivisional Lines,
T. 25 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T 25 S R 8 W
1/4
S 10 | S 11
1979

from which new bearing trees

A fir, 15 ins. diam., bears N. 83 1/4° E., 6 lks. dist., mkd. 1/4 S11 BT.

A fir, 10 ins. diam., bears S. 69 3/4° W., 14 1/2 lks. dist., mkd. 1/4 S10 BT.

N. 1° 03' E., beginning new measurement.

Ascend 35 ft. over SE. slope.

1.70 Spur, slopes S. 80° E.; desc. 65 ft. over NE. slope.

4.25 Creek, 4 lks. wide, course S. 50° E.; asc. 360 ft. over broken S. slope.

20.18 Point for the N 1/16 sec. cor. of secs. 10 and 11.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

N 1/16
S 10 | S 11
1979

from which

A fir, 8 ins. diam., bears N. 17° E., 66 lks. dist., mkd. N. 1/16 S11 BT.

A fir, 18 ins. diam., bears S. 34 1/2° W., 32 lks. dist., mkd. N. 1/16 S10 BT.

Ascend 5 ft. over broken S. slope.

20.50 Spur. slopes N. 85° E.; desc. 665 ft. over NW. slope.

39.05 Little Wolf Creek, 20 lks. wide, course S. 75° E.; asc. 30 ft. over SE. slope.

40.20 South edge of gravelled road, 25 lks wide, bears N. 75° W. and S. 75° E.

40.36 The cor. of secs. 2, 3, 10, and 11, perpetuated and recorded by Vernon R. Tracy, Deputy County Surveyor, in 1966, from original evidence no longer in existence, further perpetuated and recorded by Gary L. Langlitz, Deputy County Surveyor, in 1974, monumented with an iron rod, 5/8 in diam., firmly set, the top 8 ins. below the road surface.

Fd. Ok by B. Shaner
12/7/2000
C.S. File 65/33-18

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 36 ins. in the ground, the top 8 ins. below the surface of the road, directly over iron rod, with brass cap mkd.