

County Surveyor's Record, Douglas County, Oregon

16504

Dependent Resurvey, Portion of Subdivisional Lines,
T. 32 S., R. 7 W., Willamette Meridian, Oregon

CHAINS	
8.50	Ascend 65 ft. along steep S. slope, through heavy timber and dense undergrowth, across old logged area.
19.00	Spur, slopes S.; desc. 210 ft. over SW. slope.
25.00	Ravine, drains SW.; asc. 20 ft. over SE. slope.
32.10	Ravine, drains SE.; asc. 175 ft. over SE. slope.
39.80	Spur, slopes S.; desc. 10 ft. over SW. slope.
	Point for the 1/4 sec. cor. of secs. 8 and 17, at proportionate distance; there is no remaining evidence of the original corner.
	Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.
	T 32 S R 7 W 1/4 $\frac{S 8}{S 17}$ 1978
	from which
	A fir, 7 ins. diam., bears N. 32° W., 53 lks. dist., mkd. 1/4 S8 BT.
	A double fir, 18 ins. diam., bears S. 36° E., 29 lks. dist., mkd. 1/4 S17 BT.
	Ascend 95 ft. along S. slope.
57.00	Gravelled road, 25 lks. wide, bears N. 55° E. and S. 55° W., also ridge, bears same; desc. 215 ft. over NW. slope.
79.60	The cor. of secs. 7, 8, 17, and 18.
	Land, mountainous. Soil, rocky clay. Timber, fir, pine, oak, madrone, cedar, chinquapin, and maple; undergrowth, poison oak, hazel, manzanita, ceanothus, mountain lilac, huckleberry, blackberry, Oregon grape, and fern.
	S. 89° 19' W., bet. secs. 7 and 18.
	Descend 250 ft. along N. slope, changing to broken NW, slope, through medium timber and dense undergrowth, across old logged area.
7.60	Susan Creek Road, dirt, 15 lks. wide, bears N. and S.
19.00	Ravine, drains NE.; asc. 10 ft. over E. slope
20.07	Point for the E 1/16 sec. cor. of secs. 7 and 18.
	Set an iron post, 28 ins. long, 2 1/2 ins. diam., 20 ins. in the ground, with brass cap mkd.
	E 1/16 $\frac{S 7}{S 18}$ 1978
	from which

*FDOK
10/2013
CS 65/80-32
B-1 R. Quimby*