

# County Surveyor's Record, Douglas County, Oregon

16505

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 32 S., R. 7 W., Willamette Meridian, Oregon

CHAINS

A fir, 5 ins. diam., bears N. 49 1/2° E., 22 lks.  
dist., mkd. E 1/16 S7 BT.

A fir, 6 ins. diam., bears S. 74 1/2° W., 14 lks.  
dist., mkd. E 1/16 S18 BT.

Ascend 10 ft. over E. slope.

21.30 Spur, slopes N.; desc. 370 ft. over broken NW. slope.

40.14 The 1/4 sec. cor. of secs. 7 and 18, determined at record  
distance from the remains of the original bearing trees:

A alder, 24 ins. diam., bears N. 21° W., 37 lks.  
dist., with healed blaze. (Record, N. 5° E.)

A madrone root crown, bears S. 54° W., 47 lks.  
dist., no marks visible.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins.  
in the ground, with brass cap mkd.

T 32 S R 7 W  
1/4  $\frac{S 7}{S 18}$   
1978

from which new bearing trees

A live oak, 8 ins. diam., bears N. 55 1/2° W., 68  
lks. dist., mkd. 1/4 S7 BT.

A fir, 13 ins. diam., bears S. 7 1/4° E., 40 lks.  
dist., mkd. 1/4 S18 BT.

Land, mountainous.

Soil, rocky clay.

Timber, fir, pine, oak, chinquapin, madrone, alder,  
cedar, and yew; undergrowth, poison oak, ceanothus, hazel,  
salal, manzanita, Oregon grape, and fern.

N. 1° 12' W., bet. secs. 7 and 8.

Descend 200 ft. over NW. slope, through medium timber  
and dense undergrowth, across old logged area.

2.10 Susan Creek Road, dirt, 15 lks. wide, bears N. 40° E.  
and S. 70° W., in curve.

10.50 Ravine, drains S. 70° W.; asc. 185 ft. over SW. slope.

18.90 Susan Creek Road, dirt, 15 lks. wide, bears SE. and  
N. 80° W.

19.855 Point for the S 1/16 sec. cor. of secs. 7 and 8.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins.  
in the ground, with brass cap mkd.

S 1/16  
S 7 | S 8  
1978

from which