

County Surveyor's Record, Douglas County, Oregon

16507

Dependent Resurvey, Portion of Subdivisional Lines,
T. 32 S., R. 7 W., Willamette Meridian, Oregon

CHAINS	
	<p>A madrone, 19 ins. diam., bears N. 56° W., 39 lks. dist., with healed original blaze and scribe marks 32S R7W S6 CS BT visible on partially healed blaze. (Record, N. 62° W., 38 lks.)</p> <p>Land, mountainous. Soil, rocky clay. Timber, fir, pine, oak, madrone, cedar, chinquapin, yew, and maple; undergrowth, poison oak, manzanita, ceanothus, mountain lilac, hazel, blackberry, Oregon grape, and fern.</p>
	<p>S. 89° 31' W., bet. secs. 6 and 7.</p> <p>Ascend 60 ft. along broken S. slope, through heavy timber and dense undergrowth.</p>
40.17	<p>Point for the 1/4 sec. cor. of secs. 6 and 7, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T 32 S R 7 W 1/4 $\frac{S 6}{S 7}$ 1978</p> <p>from which</p> <p style="padding-left: 40px;">A fir, 8 ins. diam., bears N. 60° E., 32 lks. dist., mkd. 1/4 S6 BT.</p> <p style="padding-left: 40px;">A fir, 8 ins. diam., bears S. 59 1/2° W., 23 lks. dist., mkd. 1/4 S7 BT.</p> <p>Corner is located at top of ascent, slopes S.; desc. 130 ft. over SW. slope.</p>
48.20	<p>Ravine, drains S.; asc. 175 ft. over broken SE. slope.</p>
60.255	<p>Point for the W 1/16 sec. cor. of secs. 6 and 7.</p> <p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 20 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">W 1/16 $\frac{S 6}{S 7}$ 1978</p> <p>from which</p> <p style="padding-left: 40px;">A fir, 10 ins. diam., bears N. 55° E., 44 lks. dist., mkd. W 1/16 S6 BT.</p> <p style="padding-left: 40px;">A fir, 7 ins. diam., bears S. 88 1/2° E., 20 lks. dist., mkd. W 1/16 S7 BT.</p> <p>Ascend 30 ft. over SE. slope.</p>
64.80	<p>Spur, slopes SW.; desc. 180 ft. over NW. slope, changing to broken N. slope.</p>