

County Surveyor's Record, Douglas County, Oregon

16551

Corrective Dependent Resurvey of a Portion
of the Subdivisional Lines,
T. 31 S., R. 7 W., Willamette Meridian, Oregon

CHAINS

(Restoring the surveys by William H. Byars,
U. S. Deputy Surveyor, in 1872 and 1882,
and correcting the resurvey by
Owen C. Chatters II, Cadastral Surveyor, in 1974)

Beginning at the cor. of secs. 10, 11, 14, and 15, perpetuated and recorded by John M. Powell, Deputy County Surveyor, in 1970, monumented with an iron post, 1 1/4 ins. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 31 S R 7 W

S 10 S 11

S 15 S 14

1970

from which the remains of the original bearing trees

A fir stump, 60 ins. diam., bears N. 54° E., 48 lks. dist., no marks visible.

A fir snag, 50 ins. diam., bears S. 16° E., 36 lks. dist., no marks visible.

A fir, 35 ins. diam., bears S. 73° W., 53 lks. dist., with healed blaze.

A root hole, bears N. 56° W., 57 lks. dist., with a down fir alongside, 66 ins. diam., with healed blaze.

and bearing trees mkd. by Powell

A fir, 42 ins. diam., bears N. 7° E., 39 lks. dist., with healed blaze.

A fir, 12 ins. diam., bears S. 28° E., 37 lks. dist., with healed blaze.

A fir, 18 ins. diam., bears N. 72° W., 95 lks. dist., with healed blaze.

N. 2° 14' W., bet. secs. 10 and 11, marking and blazing the true line.

Descend 50 ft. over N. slope, through moderate timber and undergrowth.

- 0.90 Creek, 2 lks. wide, course N. 55° E.; asc. 35 ft. over SE slope.
- 3.80 Spur, slopes E.; desc. 15 ft. over NE. slope.
- 4.45 Creek, 2 lks. wide, course S. 85° E.; asc. 25 ft. over SE. slope.
- 7.65 Spur, slopes E.; desc. 140 ft. over NE. slope.
- 15.85 Creek, 2 lks. wide, course S. 85° E.; desc. 150 ft. over NE. slope.
- 22.50 Creek, 3 lks. wide, course S. 65° E.; asc. 210 ft. over S. slope.
- 33.35 Spur, slopes N. 80° E.; desc. 215 ft. over NE. slope.