

County Surveyor's Record, Douglas County, Oregon

Subdivision of Sec. 19,
T. 23 S., R. 7 W., Willamette Mer., Oregon

16596

CHAINS	
	<p>from which bearing trees mkd. by Brooks and Peterson in 1964</p> <p style="padding-left: 40px;">A maple, 20 ins. diam., bears S. 44 1/2° E., 48 lks. dist., with healed blaze.</p> <p style="padding-left: 40px;">A cedar, 28 ins. diam., bears S. 80 1/2° W., 58 lks. dist., with healed blaze.</p>
	<p>From the center W. 1/16 sec. cor. of sec. 19.</p> <p>N. 0° 51' E., on the N. and S. center line of the NW 1/4 of sec. 19.</p> <p>Ascend 25 ft. over SE. slope, through heavy timber and moderate undergrowth.</p>
14.20	Spur, slopes S. 30° E.; desc. 70 ft. over broken NE. slope.
19.90	Bottom of descent, drains E.; asc. 5 ft. over broken SE. slope.
20.36	<p>Point for the NW. 1/16 sec. cor. of sec. 19, at intersection with the E. and W. center line of the NW 1/4.</p> <p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins in the ground, with brass cap mkd.</p> <p style="text-align: center;">NW 1/16 S 19 1979</p> <p>from which</p> <p style="padding-left: 40px;">A fir, 74 ins. diam., bears S. 53 3/4° W., 52 lks. dist., mkd. NW 1/16 S19 BT.</p> <p style="padding-left: 40px;">A fir, 41 ins. diam., bears N. 31 1/4° W., 7 lks. dist., mkd. NW 1/16 S19 BT.</p> <p>Ascend 65 ft. over broken SE. slope.</p>
32.40	Spur, slopes E.; desc. 130 ft. over NE. slope.
37.35	Mehl Creek Road, gravelled, 15 lks. wide, bears N. 85° E. and S. 85° W.
38.25	Mehl Creek, 6 lks. wide, course N. 50° E.; ascend slightly over nearly level land.
40.72	The W. 1/16 sec. cor. of secs. 18 and 19.
	<p>From the center N. 1/16 sec. cor. of sec. 19.</p> <p>S. 89° 32' W., on the E. and W. center line of the NW 1/4 of sec. 19.</p> <p>Descend 280 ft. over gentle NW. slope, through moderate timber and dense undergrowth.</p>
15.20	Mehl Creek Road, 35 lks. wide, bears N. 10° E. and S. 10° W.
19.15	Creek, 2 lks. wide, course N.; asc. 40 ft. over general E. slope.