

County Surveyor's Record, Douglas County, Oregon

16605

Dependent Resurvey, Portion of Subdivisional Lines,
T. 33 S., R. 5 W., Willamette Meridian, Oregon

16605

CHAINS

4.61

The cor. of secs. 21, 22, 27, and 28, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd.

T 33 S R 5 W
S 21 | S 22
S 28 | S 27
1967

from which the original bearing trees

A madrone, 16 ins. diam., bears N. 45° E., 55 lks. dist., with healed blaze. (Record, N. 43 1/2 E.)

A madrone, 17 ins. diam., bears S. 40° E., 22 lks. dist., with illegible scribe marks visible on partially healed blaze.

A cedar, 30 ins. diam., bears S. 87° W., 52 lks. dist., with healed blaze.

A fir, 17 ins. diam., bears N. 54° W., 31 lks. dist., with healed blaze. (Record, N. 56° W.)

Land, mountainous.

Soil, rocky clay.

Timber, fir, pine, cedar, madrone, oak, dogwood, and yew; undergrowth, poison oak, manzanita, ocean spray, hazel, and young timber.

From the 1/4 sec. cor. of secs. 21 and 22, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd.

T 33 S R 5 W
1/4
S 21 | S 22
1968

from which the original bearing trees

A black oak, 20 ins. diam., bears S. 41° E., 57 lks. dist., with healed blaze.

A black oak, 20 ins. diam., bears N. 41° W., 40 lks. dist., with healed blaze.

and bearing trees mkd. by Aanrud

A cedar, 11 ins. diam., bears S. 10° E., 35 lks. dist., with healed blaze.

A ponderosa pine, 14 ins. diam., bears S. 88 1/2° W., 40 lks. dist., with healed blaze. (Record, S. 87 1/2° W., 41 lks.)

N. 0° 41' E., bet. secs. 21 and 22.

Ascend 3 ft. along W. slope, through medium timber and dense undergrowth.

0.80

Spur, slopes W.; desc. 70 ft. over NW. slope.

3.35

Creek, 1 lk. wide, course N. 80° W.; asc. 70 ft. over SW. slope.