

# County Surveyor's Record, Douglas County, Oregon

16616

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 33 S., R. 5 W., Willamette Meridian, Oregon

CHAINS	
	<p>S 1/16 S 20 S 21 1977</p>
	<p>from which</p> <p style="padding-left: 40px;">A fir, 20 ins. diam., bears N. 55 1/2° E., 25 lks. dist., mkd. S 1/16 S21 BT.</p> <p style="padding-left: 40px;">A fir, 21 ins. diam., bears S. 52 1/2° W., 18 1/2 lks. dist., mkd. S 1/16 S20 BT.</p> <p>Ascend 40 ft. over S. slope.</p>
21.80	Spur, slopes SE.; desc. 5 ft. over NE. slope.
25.75	Ravine, drains S. 30° E.; asc. 105 ft. over SW. slope.
29.50	Spur, slopes SE.; asc. 40 ft. over SE. slope.
34.60	Ravine, drains SE.; asc. 145 ft. over S. slope.
39.84	The 1/4 sec. cor. of secs. 20 and 21, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 6 ins. above ground, with brass cap mkd.
	<p>T 33 S R 5 W 1/4 S 20 S 21 1974</p>
	<p>from which the original bearing trees</p> <p style="padding-left: 40px;">A black oak, 17 ins. diam., bears N. 2 1/2° E., 99 lks. dist., with healed blaze.</p> <p style="padding-left: 40px;">A ponderosa pine, 26 ins. diam., bears S. 75 3/4° W., 103 lks. dist., with healed blaze.</p> <p>and a new bearing tree</p> <p style="padding-left: 40px;">A fir, 12 ins. diam., bears N. 4 1/2° E., 23 lks. dist., mkd. 1/4 S21 BT.</p> <p>Land, mountainous. Soil, rocky clay. Timber, fir, pine, cedar, oak, madrone, alder, and maple; undergrowth, poison oak, manzanita, wild berry vines, and young timber.</p>
	<p>From the cor. of secs. 15, 16, 21, and 22.</p> <p>N. 89° 09' W., bet. secs. 16 and 21.</p> <p>Descend 230 ft. over SW. slope, through scattering timber and dense undergrowth.</p>
12.50	Ravine, drains S. 40° W.; asc. 30 ft. over SE. slope.
20.47	The E 1/16 sec. cor. of secs. 16 and 21, established and recorded by Horace C. Hall, County Surveyor, in 1915, and is accepted as the corner, monumented with the point of a decayed wood post, from which the remains of a bearing tree mkd. by Hall: