

# County Surveyor's Record, Douglas County, Oregon

16640

Subdivision of Section 21, T. 33 S., R. 5 W.,  
Willamette Meridian, Oregon

CHAINS	
16.45	Gravelled road, 15 lks. wide, bears N. 10° W. and S. 10° E.; also leave open pasture, edge bears same; enter timber and undergrowth.
20.215	The center 1/4 sec. cor. of sec. 21  N. 89° 47' W., beginning new measurement.  Ascend 320 ft. over SE. slope.
15.75	Spur, slopes S. 30° E.; desc. 110 ft. along broken S. slope.
32.35	Creek, 1 lk. wide, course S. 25° E.; asc. 320 ft. over E. slope.
40.55	The 1/4 sec. cor. of secs. 20 and 21.
	From the center E 1/16 sec. cor. of sec. 21.  N. 0° 02' E., on the N. and S. center line of the NE 1/4 of sec. 21.  Descend 80 ft. along W. slope, through medium timber and dense undergrowth.
10.25	Bottom of descent, slopes S. 70° W.; asc. 35 ft. over SE. slope.
13.10	Spur, slopes S. 70° W.; desc. 15 ft. over NW. slope.
14.50	Ravine, drains S. 70° W.; asc. 55 ft. over S. slope, changing to SW. slope.
20.05	Point for the NE. 1/16 sec. cor. of sec. 21, at intersection with the E. and W. center line of the NE 1/4.  Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.  NE 1/16 S 21 1977  from which  A fir, 7 ins. diam., bears S. 20 1/2° E., 57 1/2 lks. dist., mkd. NE 1/16 S21 BT.  A fir, 10 ins. diam., bears N. 62° W., 22 1/2 lks. dist., mkd. NE 1/16 S21 BT.  Ascend slightly along broken W. slope.
26.10	Dry bed of creek in Post Gulch, 5 lks. wide, drains SW.; asc. 20 ft. over S. slope.
27.50	Spring seepage, drains S.; asc. 240 ft. over S. slope.
40.03	The E 1/16 sec. cor. of secs. 16 and 21.
	From the N 1/16 sec. cor. of secs. 21 and 22.  N. 89° 31' W., on the E. and W. center line of the NE 1/4 of sec. 21.