

County Surveyor's Record, Douglas County, Oregon

16644

Remonumentation of Certain Original Corner Points,
T. 33 S., R. 5 W., Willamette Meridian, Oregon

CHAINS

A cedar, 12 ins. diam., bears N. 73° E., 19 lks. dist., with scribe mark S visible on partially opened double blaze.

A root hole, bears S. 26° W., 30 lks. dist., with a down cedar alongside, 28 ins. diam., with healed double blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, in a mound of stone, 2 1/2 ft. base, to top, with brass cap mkd.

T 33 S
R 5 W 1/4 R 4 W
S 12 | S 7
1980

from which a new bearing tree

A fir, 28 ins. diam., bears S. 21 1/2° W., 39 lks. dist., mkd. 1/4 S12 BT.

Deposit corner stone alongside iron post.

Subdivisions, T. 33 S., R. 5 W.,
Willamette Meridian, Oregon

(Remonumenting a corner established by Edward F. Sharp,
U. S. Deputy Surveyor, in 1893-94)

The 1/4 sec. cor. of secs. 4 and 9, monumented with the original slate stone, now broken, 12 x 8 x 6 ins. (record, 14 x 12 x 6 ins.) firmly set 6 ins. in the ground, no marks visible, from which the original bearing trees:

A fir, 40 ins. diam., bears N. 45° E., 5 lks. dist., with fragmentary scribe marks visible on opened blaze.

A madrone, 14 ins. diam., bears S. 4° W., 21 lks. dist., with opened and decayed blaze, no marks visible.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, in a mound of stone, 2 1/2 ft. base, to top, with brass cap mkd.

T 33 S R 5 W

1/4 $\frac{S}{S}$ $\frac{4}{9}$
1980

from which a new bearing tree

A madrone, 9 ins. diam., bears N. 70° W., 41 lks. dist., mkd. 1/4 S4 BT.

Deposit corner stone alongside iron post.