

County Surveyor's Record, Douglas County, Oregon

16703

Remonumentation of Certain Original Corner Points,
T. 20 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

from which bearing trees marked in 1949

A fir, 14 ins. diam., bears S. 85° W., 24 lks. dist., with healed blaze.

A fir, 12 ins. diam., bears N. 2 1/4° W., 30 lks. dist., with healed blaze.

South Boundary, T. 20 S., R. 8 W.,
Willamette Meridian, Oregon

(Rehabilitating corners established by
William P. Wright, in 1883, and
remonumented by T. A. Tillman in 1950)

The cor. of Tps. 20 and 21 S., R. 8 W., on the W. bdy. of T. 21 S., R. 7 W., monumented with an iron post, 3 ins. diam., firmly set, projecting 7 ins. above ground, with brass cap mkd.

T 20 S	T 21 S
R 8 W	R 7 W
S 36	S 6
S 1	S 1
T 21 S	S 6
	1950

from which the remains of the original bearing trees

A maple snag, 22 ins. diam., bears N. 75° W., 39 lks. dist., with healed blaze.

and the remains of the bearing trees marked in 1950

A root hole, bears S. 77 1/2° W., 29 lks. dist. with a down cedar alongside, 40 ins. diam., with fragmentary scribe marks visible on partially healed blaze.

A burned and sawed fir stump, 75 ins. diam., bears N. 43° W., 93 lks. dist., with scribe marks T20S R8W S36 BT visible on open blaze.

and a new bearing tree

A hemlock, 14 ins. diam., bears S. 29 1/4° W., 80 lks. dist., mkd. T21S R8W S1 BT.

Set a 6 ft. steel fencepost alongside the iron post.

(Rehabilitating a corner reestablished by
Thomas A. Tillman, in 1950)

The 1/4 sec. cor. of secs. 31 and 36, monumented with an iron post, 1 in. diam., firmly set, projecting 8 ins above ground, with brass cap mkd.

1/4	S 36
	S 1
	1950

from which the remains of the bearing trees marked in 1950