

County Surveyor's Record, Douglas County, Oregon

16709

Remonumentation of Certain Original Corner Points,
T. 20 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

The 1/4 sec. cor. of secs. 6 and 31, monumented with an iron post, 1 in. diam., firmly set, projecting 8 ins. above ground, with brass cap mkd.

1/4 $\frac{S\ 31}{S\ 6}$
1945

from which the remains of the original bearing tree

A root hole, bears N. 41° W., 4 lks. dist., with a down and burned cedar alongside, 28 ins. diam., no marks remaining on open and burned blaze.

and the remains of the bearing trees marked in 1945

A sawed fir stump, 40 ins. diam., bears S. 69° W., 42 lks. dist., no marks remaining on open and burned blaze. Rescribed 1/4 S6 BT on new blaze.

A root hole, bears N. 31° W., 41 lks. dist., with a down and burned cedar alongside, 18 ins. diam., with scribe marks BT visible on partially open blaze.

and new bearing trees

A sawed and burned fir stump, 50 ins. diam., bears S. 57° E., 30 lks. dist., mkd. 1/4 S6 BT.

A charred cedar, 17 ins. diam., bears N. 74° W., 32 lks. dist., mkd. 1/4 S31 BT.

Set a 6 ft. steel fence post alongside the iron post.

West Boundary, T. 20 S., R. 8 W.,
Willamette Meridian, Oregon

(Rehabilitating a corner reestablished by
Thomas A. Tillman, in 1950)

The 1/4 sec. cor. of sec. 31 only, monumented with an iron post, 1 in. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd.

| 1/4 S 31
1950

from which bearing trees marked in 1950

A fir, 33 ins. diam., bears N. 57° E., 108 lks. dist., with healed blaze.

A hemlock, 28 ins. diam., bears S. 24° E., 59 lks. dist., with fragmentary scribe marks visible on burned blaze. Rescribed 1/4 S31 BT on new blaze.

Set a 5 ft. steel fence post alongside the iron post.

(Rehabilitating a corner established by
Thomas A. Tillman, and Joseph S. Gawron
in 1954)