

County Surveyor's Record, Douglas County, Oregon

16712

Remonumentation of Certain Original Corner Points,
T. 20 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

235 1/2 lks. dist., mkd. T20S R9W S24 CC BT.

(Rehabilitating a corner reestablished by
Thomas A. Tillman, Joseph S. Gawron,
Hans W. Thielsen, and Raymond M. Bicknell,
in 1954)

The 1/4 sec. cor. of sec. 19 only, monumented with an iron
post, 1 in. diam., firmly set, projecting 6 ins. above
ground, with brass cap mkd.

1/4 S 19
1954

from which bearing trees marked in 1954

A fir, 42 ins. diam., bears N. 88 1/2° E.,
107 lks. dist., with healed blaze.

A hemlock, 36 ins. diam., bears S. 56° E.,
25 lks. dist., with scribe marks 1/4 visible
on partially healed blaze.

Set a 5 ft. steel fence post alongside the iron post.

(Rehabilitating a corner established by
Thomas A. Tillman, and Joseph S. Gawron,
in 1954)

The 1/4 sec. cor. of sec. 24 only, T. 20 S., R. 9 W., on
the E. bdy. of the Tp., monumented with an iron post, 1
in. diam., firmly set, projecting 8 ins. above ground,
with brass cap mkd.

1/4 S 24
1954

from which the remains of the bearing trees marked in
1954

A hemlock snag, 14 ins. diam., bears
S. 61 3/4° W., 76 lks. dist., with scribe
marks 1/4 S24 BT visible on open blaze.

A cedar snag, 14 ins. diam., bears N. 40 1/4° W.,
50 lks. dist., no marks remaining on burned
blaze.

and new bearing trees

A hemlock, 18 ins. diam., bears S. 12° W.,
52 lks. dist., mkd. 1/4 S24 BT.

A hemlock, 30 ins. diam., bears West, 13 lks.
dist., mkd. 1/4 S24 BT.

Set a 5 ft. steel fence post alongside the
iron post.