

County Surveyor's Record, Douglas County, Oregon

16714

Remonumentation of Certain Original Corner Points
T. 20 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

26 lks. dist., no marks remaining on burned blaze. Rescribed T20S R9W S13 CC BT on new blaze.

(Rehabilitating a corner established by William P. Wright, in 1883, and remonumented by Thomas A. Tillman, Joseph S. Gawron, Hans W. Thielsen, and Raymond M Bicknell, in 1954)

The true point for the 1/4 sec. cor. of sec. 18 only, determined from the remaining bearing tree marked in 1954, this point falls in a cut bank of a gravel road and is impractical to monument.

A fir, 28 ins. diam., bears N. 41 1/4° E., 31 lks. dist., with fragmentary scribe marks visible on burned blaze.

From this point a witness corner established by the County Surveyor, in 1965, bears East, 66 1/2 lks. dist., monumented with an iron pipe, 1 in. diam., firmly set, projecting 14 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

W C
40' WEST
TO
1/4 S18
T 20 S
R 8 W
1965

from which the remains of the trees marked by the County Surveyor, in 1965

A hemlock stump, 12 ins. diam., bears N. 46° E., 7 lks. dist., with scribe marks BT visible on unhealed blaze.

Set a 6 ft. steel fence post alongside the witness corner.

(Rehabilitating a corner established by Thomas A. Tillman, and Joseph S. Gawron, in 1954)

The 1/4 sec. cor. of sec. 13 only, T. 20 S., R. 9 W., on the E. bdy. of the Tp., monumented with an iron post, 1 in. diam., firmly set, projecting 8 ins. above ground, with brass cap mkd.

1/4 S 13
1954

from which the original bearing trees

A hemlock, 37 ins. diam., bears S. 57 3/4° W., 25 lks. dist., with scribe marks 1/4 S13 BT visible on open blaze.

A hemlock, 38 ins. diam., bears N. 16 3/4° W., 81 lks. dist., with healed blaze.

Set a 5 ft. steel fence post alongside the