

# County Surveyor's Record, Douglas County, Oregon

16718

Remonumentation of Certain Original Corner Points,  
T. 20 S., R 8 W., Willamette Meridian, Oregon

CHAINS

(Rehabilitating corners reestablished by  
Thomas A. Tillman, in 1950)

The 1/4 sec. cor. of secs. 35 and 36, monumented with an iron post, 1 in. diam., firmly set, projecting 10 ins. above ground, with brass cap mkd.

1/4  
S 35 | S 36  
1950

from which the remains of the bearing trees marked in 1950

A root hole, bears N. 15° E., 21 lks. dist., with a down and burned fir alongside, 15 ins. diam., with healed blaze.

A root hole, bears S. 70° W., 22 lks. dist., with a down and burned fir alongside, 20 ins. diam., with healed blaze.

and new bearing trees

A burned fir snag, 20 ins. diam., bears S. 89 1/2° E., 49 1/2 lks. dist., mkd. 1/4 S36 BT.

A burned fir snag, 19 ins. diam., bears S. 86 1/2° W., 59 1/2 lks. dist., mkd. 1/4 S35 BT.

Set a 5 ft. steel fence post alongside the iron post.

The cor. of secs. 25, 26, 35, and 36, monumented with an iron post, 2 ins. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd.

T 20 S | R 8 W  
S 26 | S 25  
S 35 | S 36  
1950

from which the remains of the bearing trees marked in 1950

A sawed and burned fir stump, 47 ins. diam., bears N. 78° E., 104 lks. dist., no marks remaining. Rescribed T20S R8W S25 BT on new blaze.

A burned hemlock snag, 15 ins. diam., bears S. 47 3/4° E., 81 lks. dist., with fragmentary scribe marks visible on partially healed blaze. (Record, 84 lks.)

A burned hemlock snag, 14 ins. diam., bears S. 65 3/4° W., 21 lks. dist., with fragmentary scribe marks visible on partially healed blaze.

A burned fir snag, 50 ins. diam., bears N. 83 1/2° W., 94 lks. dist., no marks remaining on burned blaze. Rescribed T20S R8W S26 BT on new blaze.

Set a 6 ft. steel fence post alongside the iron post.