

County Surveyor's Record, Douglas County, Oregon

16719

Remonumentation of Certain Original Corner Points,
T. 20 S. R. 8 W. Willamette Meridian, Oregon

CHAINS

The 1/4 sec. cor. of secs. 25 and 36, monumented with an iron post, 1 in. diam., firmly set, projecting 10 ins. above ground, with brass cap mkd.

1/4 S 25
 S 36
 1950

from which the remains of the bearing trees marked in 1950

A burned fir snag, 60 ins. diam., bears N. 65° W., 25 lks. dist., with healed blaze.

A burned cedar snag, 23 ins. diam., bears S. 52° E., 44 lks. dist., no marks remaining on burned blaze. Rescribed 1/4 S36 BT on new blaze.

Set a 6 ft. steel fence post alongside the iron post.

The 1/4 sec. cor. of secs. 25 and 26, monumented with an iron post, 1 in. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd.

1/4
S 26 | S 25
1950

from which the remaining bearing tree marked in 1950

A hemlock, 37 ins. diam., bears N. 3 3/4° W., 29 lks. dist., with healed blaze.

and a new bearing tree

A burned cedar, 37 ins. diam., bears S. 59 1/2° E., 60 1/2 lks. dist., mkd. 1/4 S25 BT.

Set a 6 ft. steel fence post alongside the iron post.

(Rehabilitating a corner established
by William P. Wright, in 1884, and
remonumented by Thomas A. Tillman, in 1950)

The cor. of secs. 23, 24, 25, and 26, monumented with an iron post, 2 ins. diam., firmly set, projecting 6 ins. above ground, with brass cap mkd.

T 20 S R 8 W
S 23 | S 24
S 26 | S 25
1950

from which the remains of the bearing trees marked in 1950

A burned cedar snag, 48 ins. diam., bears N. 15 1/2° E., 75 lks. dist., with scribe marks S R8W S24 T visible on partially healed and burned blaze.