

County Surveyor's Record, Douglas County, Oregon

16720

Remonumentation of Certain Original Corner Points,
T. 20 S., R 8 W., Willamette Meridian, Oregon

CHAINS

A burned hemlock snag, 55 ins. diam., bears
S 26° W., 113 lks. dist., with scribe marks
T20S R8W S25 BT visible on open and burned blaze.

A burned hemlock snag, 37 ins. diam., bears
S. 36 1/2° W., 51 lks. dist., with scribe marks
T20S R8W S26 BT visible on open and burned blaze.

A burned cedar snag, 70 ins. diam., bears
N. 67 1/2° W., 58 lks. dist., with scribe marks
T20S R8W S23 BT visible on open and burned blaze.

Set a 6 ft. steel fence post alongside the
iron post.

(Rehabilitating a corner reestablished by
Thomas A. Tillman, in 1950)

The 1/4 sec. cor. of secs. 24, and 25, monumented with an
iron post, 1 in. diam., firmly set, projecting 14 ins.
above ground, with brass cap mkd.

1/4 $\frac{S\ 24}{S\ 25}$
1950

from which the remains of the bearing trees marked in
1950

A burned hemlock snag, 46 ins. diam., bears
N. 36° W., 60 lks. dist., with healed blaze.

A burned hemlock snag, 26 ins. diam., bears
S. 9° W., 26 lks. dist., with fragmentary
scribe marks visible on partially healed
and burned blaze.

Set a 6 ft. steel fence post alongside the iron
post.

(Rehabilitating corners reestablished by
Thomas A. Tillman, Joseph S. Gawron,
Hans W. Thielsen, and Raymond M. Bicknell, in 1954)

The 1/4 sec. cor. of secs. 23 and 24, monumented with an
iron post, 1 in. diam., firmly set, projecting 10 ins.
above ground, with brass cap mkd.

1/4
S 23 | S 24
1954

from which the remains of the bearing trees marked in
1954

A burned snag, 65 ins. diam., bears
N. 23 1/4° E., 83 lks. dist., no marks
remaining on burned blaze. Rescribed 1/4
S24 BT on new blaze.

A burned fir snag, 38 ins. diam., bears
N. 21 1/4° W., 106 lks. dist., no marks