

# County Surveyor's Record, Douglas County, Oregon

16722

Remonumentation of Certain Original Corner Points,  
T. 20 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

T 20 S R 8 W  
S 11 | S 12  
S 14 | S 13  
1954

from which the remains of the bearing trees marked in 1954

A root hole bears N. 47° E., 68 lks. dist., with a down and burned fir alongside, 28 ins. diam., no marks visible.

A fir, 37 ins. diam., bears S. 60° E., 47 lks. dist., no marks remaining on burned blaze. (Record, S. 62 1/2° E., 45 lks.) Rescribed T20S R8W S13 BT on new blaze.

A fir, 30 ins. diam., bears S. 18° W., 24 lks. dist., no marks remaining on burned blaze. (Record, S. 22° W.)

A fir, 34 ins. diam., bears N. 13 1/2° W., 73 lks. dist., with burned blaze. (Record, N. 16 3/4° W.) Rescribed T20S R8W S11 BT

and a new bearing tree

A fir, 35 ins. diam., bears N. 54° E., 29 lks. dist., mkd. T20S R8W S12 BT.

(Rehabilitating a corner reestablished by Thomas A. Tillman, Raymond M. Bicknell, Hans W. Thielsen, and Joseph S. Gawron, in 1954, and rehabilitated by Floyd A. Brooks, in 1960)

The 1/4 sec. cor. of secs. 12 and 13, monumented with an iron post, 1 in. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd.

1/4 S 12  
S 13  
1954

from which the remains of the bearing trees marked in 1954

A stump hole, bears N. 9° E., 52 lks. dist.,

A stump hole, bears S. 41° E., 33 lks. dist.,

and the remains of the bearing trees marked in 1960

A root hole, bears N. 47° E., 34 lks. dist., with a down cedar alongside, 8 ins. diam., no marks visible.

A root hole, bears S. 44° E., 88 lks. dist., with a down cedar alongside, 14 ins. diam., with fragmentary scribe marks visible on open and burned blaze.

and new bearing trees

A fir stump, 36 ins. diam., bears S. 10° W., 56 lks. dist., mkd. 1/4 S13 BT.