

County Surveyor's Record, Douglas County, Oregon

16725

Remonumentation of Certain Original Corner Points,
T. 20 S., R. 8 W., Willamette Meridian, Oregon

23

CHAINS

and burned blaze.

A burned alder snag, 25 ins. diam., bears
S. $31\frac{1}{2}^{\circ}$ E., 116 lks. dist., with scribe
marks T20 visible on partially healed and
burned blaze.

A burned cedar snag, 40 ins. diam., bears
S. $69\frac{1}{4}^{\circ}$ W., 125 lks. dist., no marks
remaining on burned blaze. Rescribed
T20S R8W S34 BT on new blaze.

A burned and sawed fir stump, 27 ins. diam.,
bears N. $39\frac{3}{4}^{\circ}$ W., 186 lks. dist., with
fragmentary scribe marks visible on partially
healed and burned blaze.

Set a 6 ft. steel fence post alongside the iron
post.

The $\frac{1}{4}$ sec. cor. of secs. 26 and 35, monumented with an
iron post, 1 in. diam., firmly set, projecting 10 ins.
above ground, with brass cap mkd.

$$\frac{1}{4} \begin{array}{l} S\ 26 \\ S\ 35 \end{array}$$

1950

from which the remains of the bearing trees marked in
1950

A burned fir snag, 26 ins. diam., bears
N. $17\frac{1}{2}^{\circ}$ E., 50 lks. dist., with healed blaze.

A burned fir snag, 60 ins. diam., bears
S. $83\frac{1}{4}^{\circ}$ E., 44 lks. dist., with healed blaze.

Set a 6 ft. steel fence post alongside the iron
post.

The $\frac{1}{4}$ sec. cor. of secs. 26 and 27, monumented with an
iron post, 1 in. diam., firmly set, projecting 6 ins.
above ground, with brass cap mkd.

$$\frac{1}{4} \begin{array}{l} S\ 27 \\ S\ 26 \end{array}$$

1950

from which the remains of the bearing trees marked in
1950

A burned and sawed fir stump, 60 ins. diam.,
bears S. 5° E., 40 lks. dist., with healed
blaze.

A burned cedar snag, 38 ins. diam., bears
S. 80° W., 68 lks. dist., with fragmentary
scribe marks visible on burned blaze.

Set a 6 ft. steel fence post alongside the iron
post.

(Rehabilitating a corner established by William P. Wright,
in 1884, and remonumented by Thomas A. Tillman, in 1950)