

County Surveyor's Record, Douglas County, Oregon

16726

Remonumentation of Certain Original Corner Points,
T. 20 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

The cor. of secs. 22, 23, 26, and 27, monumented with an iron post, 2 ins. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd.

T 20	S	R 8	W
	S 22	S 23	
	S 27	S 26	
1950			

from which the remains of the bearing trees marked in 1950

A burned fir snag, 20 ins. diam., bears N. 85 1/2° E., 22 lks. dist., no marks remaining on burned blaze. Rescribed T20S R8W S23 BT on new blaze.

A burned fir snag, 21 ins. diam., bears S. 66 1/2° E., 17 lks. dist., no marks remaining on burned blaze.

A burned fir snag, 62 ins. diam., bears S. 7° W., 43 lks. dist., no marks remaining on burned blaze.

A burned fir snag, 46 ins. diam., bears N. 23 1/2° W., 40 lks. dist., no marks remaining on burned blaze. Rescribed T20S R8W S22 BT on new blaze.

and a new bearing tree

A burned fir snag, 39 ins. diam., bears S. 31° W., 24 1/2 lks. dist., mkd. T20S R8W S27 BT.

Set a 6 ft. steel fence post alongside the iron post.

(Rehabilitating corners reestablished by
Thomas A. Tillman, in 1950)

The 1/4 sec. cor. of secs. 23 and 26, monumented with an iron post, 1 in. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd.

1/4	S 23
	S 26
1950	

from which the remains of the bearing trees marked in 1950

A burned fir snag, 20 ins. diam., bears N. 76 1/4° W., 34 lks. dist., with healed blaze.

A burned and sawed hemlock stump, 32 ins. diam., bears S. 13 1/2° E., 31 lks. dist., with healed blaze.

Set a 6 ft. steel fence post alongside the iron post.

The 1/4 sec. cor. of secs. 22 and 23, monumented with an iron post, firmly set, projecting 6 ins. above ground,