

County Surveyor's Record, Douglas County, Oregon

16727

Remonumentation of Certain Original Corner Points,
T. 20 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

with brass cap mkd.

$$\begin{array}{c} 1/4 \\ S\ 22\ | \ S\ 23 \\ 1950 \end{array}$$

from which the remains of the bearing trees marked in 1950

A burned and sawed fir stump, 56 ins. diam., bears S. 66° W., 57 lks. dist., no marks remaining on burned blaze.

and a new bearing tree

A burned cedar, 10 ins. diam., bears S. 86° E., 27 lks. dist., mkd. 1/4 S23 BT.

Set a 6 ft. steel fence post alongside the iron post.

(Rehabilitating a corner established by William P. Wright, in 1884, and remonumented by Thomas A. Tillman, in 1950)

The cor. of secs. 14, 15, 22, and 23, monumented with an iron post, 2 ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd.

$$\begin{array}{c} T\ 20\ S\ R\ 8\ W \\ S\ 15\ | \ S\ 14 \\ S\ 22\ | \ S\ 23 \\ 1950 \end{array}$$

from which the remains of the bearing trees marked in 1950

A burned and sawed fir stump, 52 ins. diam., bears S. 13 3/4° W., 161 lks. dist., with fragmentary scribe marks visible on partially healed and burned blaze. Rescribed T20S R8W S22 BT on new blaze.

A root hole, bears N. 79° W., 91 lks. dist., with a down and burned fir alongside, 52 ins. diam., no marks remaining on burned blaze.

and new bearing trees

A burned and sawed fir stump, 62 ins. diam., bears N. 25 1/2° E., 103 1/2 lks. dist., mkd. T20S R8W S14 BT.

A burned and sawed fir stump, 60 ins. diam., bears S. 68 1/2° E., 164 lks. dist., mkd. T20S R8W S23 BT.

A burned fir, 62 ins. diam., bears N. 78 1/2° W., 163 lks. dist., mkd. T20S R8W S15 BT.

Set a 6 ft. steel fence post alongside the iron post.

(Rehabilitating corners reestablished by Thomas A. Tillman, Joseph S. Gawron, Hans W. Thielsen, and Raymond M. Bicknell, in 1953-54)